



Overview: Part of spill impact on 28" Bomu Bonny Trans Niger Pipeline at Owokiri.
Picture was taken during Joint Investigation of 14th August 2021.



Close-up : Failed 6inch ball valve flange on 28" Bomu Bonny Trans Niger Pipeline at Owokiri.
Picture was taken during Joint Investigation of 14th August 2021.