

<u>Overview:</u> Part of spill impact on 20'' Kolocreek-Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 31st December 2021.



<u>Close-up:</u> 3inch ball valve with 3inch elbow connection installed at 12 o'clock position on 20'' Kolocreek - Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 31st December 2021.