



Overview: Part of spill impact on 6'' Belema Delivery line Right of Way at Belema. Picture was taken during Joint Investigation of 20th December 2021.



Close-up: 20mm Rough-edge Hole due to corrosion at 6 o'clock position on 6'' Belema Delivery line at Belema. . Picture was taken during Joint Investigation of 20th December 2021.