

JOINT INVESTIGATION REPORT

INCIDENT NO: 2999627 JIV report S/N: 0000946

(Note: As practicable as possible the JIR report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Fountain Incident Number: 2999627 2. Type of incident: OIL SPILL
3. Name of Location: 20" KORO CREEK - RUMUEKPE TRUNKLINE
4. Name of nearest community: IHUONO 5. State: RIVERS 6. LGA: AHIAZA EAST
7. Production Facility/Installation: OIL PIPELINE
8. Asset Owner/Hub: THE SHELL PETROLEUM DEVELOPMENT COMPANY

B. INCIDENT INFORMATION:

9. Details of incident
a. Date Reported: 27TH JULY, 2021
b. Start date/time of Investigation: 29TH JULY, 2021 15:00 HRS
c. Investigation End date: 29TH JULY, 2021 Day(s) on site: ONE (1) DAY
d. Description of spill point environment
 Firm soil Loose soil Recently excavated area
 Under water Swampy Exposed pipe surface
 Well Platform (on water) Drill Rig Sand bag(s)

Additional observations around the spill point:

NOT APPLICABLE

e. Description of leak point (tick as applicable):

- | | | |
|--|---|--|
| <input type="checkbox"/> Smooth round-edge hole | <input checked="" type="checkbox"/> Rough-edge hole | <input type="checkbox"/> Hack saw cut |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input checked="" type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Tear (_____) | | |
| <input type="checkbox"/> Others (specify) _____ | | |

f. Incident caused by:

- Third party interference (Sabotage crude theft ; Line theft ; Accidental 3rd party damage
 Operational Others (including Mystery spills) _____

*This can be (a) Oil Spill (b) Drilling fluid/Chemical (c) Situation (d) Water Leak (e) Fire (f) Non-leaking theft point removal
Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);
Blue (Host Community)

JOINT INVESTIGATION REPORT

000946

INCIDENT NO: 2999627 JIV report S/N:

g. Spill Point Coordinates (*Incidents $\leq 100m$ apart to be aggregated into one Joint Investigation Report)

h. Measuring unit

Northing:	Easting:
<u>4.97502</u>	<u>6.66361</u>

C. RISK ASSESSMENT

10. Details of Environment

i. Type of environment where spill occurred (select one):

Land Swamp Water Seasonal swamp Shoreline/Waterfront

ii. Type of environment to which oil has spread:

Land Swamp Waterbody (specify) _____

iii. Weather condition

Dry Wet Windy Hot

11. Distance to Sensitive habitat within 100m radius

- Government reserved and designated protected area [,m]
- Drinking water source [,m]
 - Surface water Borehole
- Built up Area [,m]
 - Residential Area Commercial/Industrial Area
- Farmlands [,m]
- Fish Farm/Pond [,m]
- Fishing net [,m]
- Others (specify) _____ [,m]

NONE SEEN
WITHIN VICINITY

12. Containment measures put in place:

Booms Trench Dyke Pit Natural depression None

Others: _____

13. Any pictures or video coverage? [] [N]

14. Further response/repair initiated as at the time of JIV? [] [N]

If yes to item 14, give brief description:

REPAIR BY CLAMPING

JOINT INVESTIGATION REPORT

INCIDENT NO: 2999627 JIV report S/N: 0000946

15. Was there any disruption to the investigation? [Y] [N] [Y] [N]

If yes to item 15 give brief description

NOT APPLICABLE
NOT APPLICABLE

16. Was JIV delayed? [Y] [N] [Y] [N]

Reason(s):

- Delayed Community Access Approval Security Challenges Access constraint due to terrain
 Others (specify) NOT APPLICABLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	<u>NONE WITHIN AREA OF IMPACT</u>				

18. Crops Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	<u>NONE WITHIN AREA OF IMPACT</u>					

19. Fish Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	<u>NONE WITHIN AREA OF IMPACT</u>			

20. Others (Specify) e.g. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	<u>NONE WITHIN AREA OF IMPACT</u>			

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detailed description of the leak point should be contained in the leak report, overview sketch of the site should be added as appendix 1)

A SECTION OF 20" KOLO CREEK - RUMUEKPE TRUNKLINE AT HUMAN STAFF WORK ROUGH-EDGE HOLE AT 12 O'CLOCK POSITION BY UNKNOWN PERSON(S)



JOINT INVESTIGATION REPORT

INCIDENT NO: 2999/27 JIV report S/N: 000946

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

2) Impacted area boundary Coordinates (If more, Print and attach as Appendix)

S/N	Northing	Easting
1	4.975018	6.663614
2	4.974988	6.66363
3	4.974949	6.663625
4	4.97499	6.663581
5	4.974943	6.663631
6	4.974949	6.663493
7	4.974978	6.662857
8	4.974833	6.663457
9	4.974829	6.662788
10	4.974699	6.662425
11	4.974525	6.662483

JOINT INVESTIGATION REPORT

INCIDENT NO: 2999627 JIV report S/N: 0000946

G. INCIDENT INFORMATION:

a. Impacted Area Details *

- Total calculated area of impact (Ha) 0.18 HECTARES
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W YES

* Round off to 2 decimal places if area is $\geq 100 \text{ m}^2$ or to 4 decimal places if area is $< 100 \text{ m}^2$ (e.g. 14.55, 0.0051, 0.00099)

* Express in Hectares (Ha)

b. Volume of oil recovered before completion of JIV (V_{rec}):

Recovered oil V_{rec} :	<u>NIL</u>	Barrels
----------------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------


c. Net Estimated Spilled Volume V_{est} (bbls)* = 24.57 BARRELS

Estimated Reported Volume** V_{rep} (bbls) = 25 BARRELS

*Notes

- Volume estimation was done using an excel based tool (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill



Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site. Conversion of m^3 to barrels is Volume (m^3) $\times 6.29$. **Round up estimated volume to next whole number using the following rules

- Any spill volume in excess of 1 bbl is rounded up to the next whole number
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl

Examples
Calculated volume = 15.3 bbl — Reported volume = 16 bbl
Calculated volume = 0.35 bbl — Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl — Reported volume = 0.1 bbl

Whenever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation, record the calculation in a plain sheet of paper and attach to the JIV report

Version 2020/01

Distribution of copies: White (Asset Owner), Pink (DPR), Green (NOSDRA), Yellow (State Ministry of Environment),
Blue (Host Community)

JOINT INVESTIGATION REPORT

INCIDENT NO: 2999627 JIV report S/N: 000946

d. General Status of the site

- i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
- ii. Investigation of the incident site showed that there is residual impact on site requiring further works

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community:
- Department of Petroleum Resources (DPR):
- National Oil Spill Detection and Response Agency (NOSDRA):
- State Ministry of Environment (SME):
- The Shell Petroleum Development Company (SPDC):
- *Separate DPR form has been filled out with same findings*
- *Separate NOSDRA form has been filled out with same findings*
- *Separate SME form has been filled out with same findings*

Tick as applicable

Version 2020/01


Distribution of copies. White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

Page 6 of 8

JOINT INVESTIGATION REPORT

INCIDENT NO: 299962 / JIV report S/N: 10000948

Appendix 1: Overview sketch of the site



Version 2020/01

Distribution of copies: White (Asset Owner) Pink (DPR) Green (NOSDRA) Yellow (State Ministry of Environment) Blue (Host Community)