

JOINT INVESTIGATION REPORT

INCIDENT NO: 2889953 JIV report S/N: 0000799

(Note: As practicable as possible the JIV report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:

1. Fountain Incident Number: 2889953 2. Type of incident* OIL SPILL
3. Name of Location 20" RUMUEKPE - NIKPOKU TRUNKLINE (PIPELINE)
4. Name of nearest community MBODO-ALUU 5. State: RIVERS 6. LGA IKWERRE
7. Production Facility/Installation PIPELINE
8. Asset Owner/Hub THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED (SPDC) / PIPELINE

B. INCIDENT INFORMATION:

9. Details of incident
a. Date Reported: 17TH MARCH, 2021
b. Start date/time of Investigation: 19TH MARCH, 2021. 12:10HRS
c. Investigation End date: 19TH MARCH, 2021 Day(s) on site: ONE (1) DAY
d. Description of spill point environment

- | | | |
|---|-------------------------------------|---|
| <input type="checkbox"/> Firm soil | <input type="checkbox"/> Loose soil | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water | <input type="checkbox"/> Swampy | <input type="checkbox"/> Exposed pipe surface |
| <input type="checkbox"/> Well Platform (on water) | <input type="checkbox"/> Drill Rig | <input type="checkbox"/> Sand bag(s) |

Additional observations around the spill point:

e. Description of leak point (tick as applicable);

- | | | |
|--|---|--|
| <input type="checkbox"/> Smooth round-edge hole | <input type="checkbox"/> Rough-edge hole | <input type="checkbox"/> Hack saw cut |
| <input type="checkbox"/> Complete Rupture | <input type="checkbox"/> Inward dent, | <input type="checkbox"/> Well head tampering |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve | <input type="checkbox"/> Failed Clamp, | <input type="checkbox"/> Missing Pipeline/Flowline |
| <input checked="" type="checkbox"/> Crude oil theft (illegal bunkering) point, | <input type="checkbox"/> Saver-pit over flow | <input type="checkbox"/> Third party tampering with Clamp |
| <input type="checkbox"/> Third party tampering with valve setting | <input type="checkbox"/> Bulging Outward | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Cold vent | <input type="checkbox"/> Surge vessel overflow, |
| <input type="checkbox"/> Valve Failure | <input type="checkbox"/> Relief valve failure | <input type="checkbox"/> Accidental 3 rd party equipment impact |
| <input type="checkbox"/> Tear (_____) | | |
| <input type="checkbox"/> Others (specify) _____ | | |

f. Incident caused by:

- ☒ Third party interference (Sabotage ☐; crude theft ☒; Line theft ☐; Accidental 3rd party damage ☐
☐ Operational ☐ Others (including Mystery spills) _____

*This can be: (a) Oil Spill (b) Drilling fluid/Chemical (c) Siltation (d) Water Leak (e) Fire (f) Non-leaking theft point removal

Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment); Blue (Host Community)

JOINT INVESTIGATION REPORT

000799

INCIDENT NO: 2889953 JIV report S/N:

g. Spill Point Coordinates (*Incidents $\leq 100m$ apart to be aggregated into one Joint Investigation Report)

h. Measuring unit

WGS 84

Northing: LATITUDE	Easting: LONGITUDE
4.93910	6.95507
/	/
/	/

C. RISK ASSESSMENT

10. Details of Environment

i. Type of environment where spill occurred (select one):

☒ Land

☐ Swamp

☐ Water

☐ Seasonal swamp

☐ Shoreline/Waterfront

ii. Type of environment to which oil has spread:

☒ Land

☐ Swamp

☐ Waterbody (specify) _____

iii. Weather condition

☐ Dry

☒ Wet

☐ Windy

☐ Hot

11. Distance to Sensitive habitat within 100m radius

☐ Government reserved and designated protected area

[NIL ,m]

☐ Drinking water source

[NIL ,m]

☐ Surface water

☐ Borehole

☐ Built up Area

[20 ,m]

☒ Residential Area

☐ Commercial/Industrial Area

☐ Farmlands

[20 ,m]

☐ Fish Farm/Pond

[NIL ,m]

☐ Fishing net

[NIL ,m]

☐ Others (specify) _____

[,m]

12. Containment measures put in place:

☐ Booms

☐ Trench

☐ Dyke

☐ Pit

☐ Natural depression

☒ None

☐ Others: _____

13. Any pictures or video coverage?

☒ [N]

14. Further response/repair initiated as at the time of JIV?

☒ [N]

If yes to item 14, give brief description:

REPAIR BY CLAMPING ONGOING.

Version 2020/01

JOINT INVESTIGATION REPORT

INCIDENT NO: 2889953 JIV report S/N: 0000799

15. Was there any disruption to the investigation? [Y] [N] ☒

If yes to item 15 give brief description:

NOT APPLICABLE

16. Was JIV delayed? [Y] [N] ☒

Reason(s): NOT APPLICABLE

- ☐ Delayed Community Access Approval ☐ Security Challenges ☐ Access constraint due to terrain
☐ Others (specify) _____

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

17. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
<u>NONE WITHIN AREA OF IMPACT</u>					

18. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
<u>NONE WITHIN AREA OF IMPACT</u>						


19. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

20. Others (Specify) e.g. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
<u>NONE WITHIN AREA OF IMPACT</u>				

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detailed description of the leak point should be contained in the leak report, overview sketch of the site should be added as appendix 1) A SECTION 20" RUMUEKPE - NKPOKU TRUNKLINE (PIPELINE) AT MBODO - ALUO SHOWING A 2" ILLEGAL CONNECTION INSTALLED AT 12 O'CLOCK POSITION BY UNKNOWN PERSON(S)



FROM RUMUEKPE - NKPOKU MANIFOLD Version 2020/01

JOINT INVESTIGATION REPORT

INCIDENT NO: 2889953 JIV report S/N: 0000799

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

21. Impacted area boundary Coordinates (If more, Print and attach as Appendix) WGS 84

S/N	Northing	LATITUDE	Easting	LONGITUDE
281		4.93909		6.95511
282		4.9391		6.95503
283		4.93913		6.95506
284		4.93911		6.95511

JOINT INVESTIGATION REPORT

INCIDENT NO: 2889953 JIV report S/N: 0000799

G. INCIDENT INFORMATION:

a. Impacted Area Details *

- Total calculated area of impact (Ha) 0.002269Ha
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W NIL

* Round off to 2 decimal places if area is $\geq 100 \text{ m}^2$ or to 4 decimal places if area is $< 100 \text{ m}^2$ (e.g. 14.55, 0.0051, 0.0009)

* Express in Hectares (Ha)

b. Volume of oil recovered before completion of JIV (V_{recJ}):

Recovered oil V_{recJ} :	<u>NIL</u>	Barrels
-----------------------------------	------------	---------

Controlled recovery/evacuation from source with no impact to environment:

<u>NIL</u>	Barrels
------------	---------

c. Net Estimated Spilled Volume $V_{\text{Est}}(\text{bbls})^* =$ 1.49 BARREL

Estimated Reported Volume** $V_{\text{rep}}(\text{bbls}) =$ 2 BARRELS

*Notes:

- Volume estimation was done using an excel based tool. (see attached for details on the calculation)
- Reported spilled volume is an estimate

Write other relevant notes taken into consideration for volume estimation or cause of spill:

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m^3) $\times 6.29$; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl
Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

Version 2020/01

Distribution of copies : White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);
Blue (Host Community)

JOINT INVESTIGATION REPORT

INCIDENT NO: 2889953 JIV report S/N: 000799

d. General Status of the site

- i. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out ☐
- ii. Investigation of the incident site showed that there is residual impact on site requiring further works ☒

e. Representatives

This report was filled, agreed and signed by the following joint investigation team representatives:

- Host Community: ☒
- Department of Petroleum Resources [DPR]: ☒
- National Oil Spill Detection and Response Agency [NOSDRA]: ☒
- State Ministry of Environment [SME]: ☒
- The Shell Petroleum Development Company [SPDC]: ☒
- *Separate DPR form has been filled out with same findings* ☒
- *Separate NOSDRA form has been filled out with same findings* ☒
- *Separate SME form has been filled out with same findings* ☒

Tick as applicable


Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);
Blue (Host Community)

JOINT INVESTIGATION REPORT

INCIDENT NO: 2889953 JIV report S/N: 0000799

f. Appendix 1: Overview sketch of the site



Version 2020/01

Distribution of copies: White (Asset Owner); Pink (DPR); Green (NOSDRA); Yellow (State Ministry of Environment);
Blue (Host Community)