



Overview: Location of spill around 2" Yokri Well127T Gas Lift Line at Yokri. Picture was taken during Joint Investigation of 21st December 2016.



Close-up: Position of missing valve on 2" Yokri Well127T Gas Lift Line at Yokri. Picture was taken during Joint Investigation of 21st December 2016.