



Overview: Part of spill impact on 4" Yokri Well 114L Flowline Right of Way at Yokri. Picture was taken during Joint Investigation of 17th January 2015.



Close-up: Spill due to corrosion on 4" Yokri Well 114L Flowline at Yokri. Picture was taken during Joint Investigation of 17th January 2015.