#### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1005316 JIV report S/N: 0090 (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 1. Spill incident Number: 1005316 2. Type of incident\* DIL SPILL \_ RUMUEKPE NKPOKU PIPELINE IBAA 5. State: RIVERS 6. LGA EMOHUA 4. Name of nearest community 7. Type of Production facility/Installation DIL PIPEL INE 8. Asset owner/District PIPELINE B. INCIDENT INFORMATION: 9. Details of incident a. Date of incident: 9TH July 2013 b. Start date/time of investigation: 12TH July 2013 / 13:48 Hours c. Investigation End date: 12TH July 2013 Actual investigation duration, days: ONE (1) DAY. a. Date of incident: 9TH d. Description of spill point environment Recently excavated area Loose soil ☐Firmed soil Exposed pipe surface Under water □Drill Rig ☐ Well Platform (on Water) e. Description of leak point (tick as applicable); ☐Hack saw cut ☐ Tear (\_\_\_\_\_\_), Drilled hole ☐Well head tampering ☐Inward dent. Complete Rupture ☐Missing Pipeline/Flowline ☐ Failed Weld-on illegal hot tap valve, ☐ Failed Clamp ☐ Third party tampering with Clamp Crude oil theft (illegal bunkering) point, ☐ Third party tampering with flange, ☐ Third party tampering with valve setting, ☐Surge vessel overflow, ☐Saver-pit over flow, ☐ Corrosion □Flare System/Bund wall failure □Accidental 3rd party equipment ☐Bulging Outward Com unit failure ☐Cold vent □Valve Failure impact Others (specify) Relief valve failure f. Incident caused by: Third party interference (Sabotage , crude theft□; Line theft□; Accidental 3<sup>rd</sup> party damage□) Others (including Mystery spills) g. Spill point coordinates Measuring unit Northing: SP 485765.05mE 105600.53mN

Page 1 of 9

JOINT INVESTIGATION RE	PORT FOR INC	DENT NO:	100531	JIV rep	ort S/N: 0	090
C. RISK ASSESSMEI						•
10. Type	of environment:					
Land	Swamp	<b>W</b> ater Water	Seas	onal swamp□S	horeline/Wa	terfront
i. Type o	f environment to v	which oil has	spread:			
Land	Swamp	□Water	□Rive	r (identify)		
ii. Weath	er condition					
☐Rain 11. Distance from t	Sunny he nearest sensitiv	□Dry e habitat	□Wet	□Windy	□Hot	□cool
☐ Drinking w ☐ Built up are ☐ Farmlands ☐ Fish Farm/l ☐ Fishing net ☐ Others (spe	ea Pond ecify).		cted area	[ ,m] [ ,m] [ ,m] [ ,m] [ ,m]	tsh fon 2 ya	D IMPACTED PILL,
12. Containment me	easures put in plac	e;	,			
□Booms □Others:	Trench	□Dyke	Natu	ıral depression	□Pit	
13. Any pictures or	video coverage?			[X] [N]		
14. Was there any d	lisruption to the in	vestigation?		[Y] [N <b>)</b>		
If yes give brief descripti	ion:	AP	PL	IC/	\BI	E

# D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

#### 15. Structures / Properties

S/N	Type of Structures	Description	Size	Number		Comments
2.				1		
N	NHE 1	MITH	1	AREA	UE	IMPACT
	UIL	<b>V</b>	111 🔻	7 11/2/	<del>UI</del>	11711716
			-			

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1005316 JIV report S/N: 0090

16.	Crops/Economic Trees	S			

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1	COCOYAM	<b>V</b>			12 _	WITHIN
2	PINE APPLE	···			15_	I -
2	PALM TRES				5	SPILL-
		<u>-</u>				IMPACTED
						REGION.
	-	-				INDIANA.

#### 17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	FISH POND	NATURAL	l No.	MITHIN SPILL-
				IMPACTED REGION,
			_	
		<u> </u>		
	<del></del>			

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
1	BIRD	HUMMING BIRD	I No.	FOUND SEAS AND
_				IMPACTED BY SPILL.
		-		

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

PLAN SECTION OF 20" RUMUEKPE - NKPOKU PIPELINE AT IBAA SHOWING POSITION OF DRILLED HOLE.



FROM RUMUEKPE TO NKPOKU

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1005316 JIV report S/N: 0090

# F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 19. Impacted area boundary Coordinates (If more, Print and attach\_asign appendix)

19. Impacted area boundary Coordinates (if mo	- Mid Self appendix)
S/N Northing (m)	<u> </u>
WP 480 105606.73	485743.49
WP 482 105 619.00	485749.69
WP483 105625.12	485758.95
WP484 105640.47	485765.15
W485 105649.67	485771.33
WY86 105661.93	485783.69
WY487 105674.178	485799.13
47488 105701.80	485811.52
WP489 105723.24	485836.23
W490 105729.30 W491 105591.38	485870.13
W491 105591 38	485737.29
W492 105591.19	485814.32
W493 105566.75	485758.80
WRL494 105429 · 83	485780.05
WL495 105426.65	485797.51
WPL496 105 435. 65	485829.79
WPL497 105435.65	485857.84
WPL498 105435.12	485866.83
WPL499 105438.29	485890.64
4L500 105465.81	485 944.09
WP1501 105492. 80	485 971.61
WPL 502 105 497.56	485497.56
MPL503 105593.87	485 112.01
VPL SOL 105683.83	485019.76
WPL 490 105708. 17 WPL 492 105512. 91	445 944 · 35
FRZ 105 633 02 Pag	48576.98 48576.23
FRZ 105 633, 02 Pag	e4019 485 800 · 16
123 105 635. 15 124 105 597. 57	485880.06 485941.44
FRS 10554+.30	485 908 . 64
126 10049 C. WW	48C824 . 80

OINT INVESTIGATION REPORT FOR INCIDENT NO: 1005316 JIV report S/N: UU7U
G. INCIDENT INFORMATION:
20. Impacted Area Details
• Total calculated area of impact 6.805802 ha (6.81 ha)
Impact within SPDC R.O.W
Impact outside SPDC R.O.W
21. Volume of oil recovered before completion of JIV (V <sub>recJ</sub> ):
Recovered oil V <sub>recj</sub> : NIL Barrels
22. Computation of estimated residual volume on site
<ul> <li>a. Computation of estimated volume of pool of free phase oil (on land or confined water body).</li> <li>i. Area (m²) occupied by pool of free phase oil 47,653</li> </ul>
ii. Average Depth (m) of pool of free phase oil
iii. Emulsification factor: NIL
iv. Estimated Volume of pool of free phase oil. V <sub>pool</sub> : 899.21 barrels
b. Computation of estimated volume of infiltrated oil in the soil (V <sub>int</sub> ).  1. Estimated Volume of infiltrated oil at spill point (Vinf a)  i. Area* (m²) of soil covered by the oil:  ii. Average Depth (m) above leaking facility i.e. pipeline/flowline:  iii. Soil type: CLAY iv. Pe (effective porosity of the soil).  v. Cause of spill: in the Ference vi. Oil type: Bonny Me Dum  vii. Oil Residence time on site, day: 3 DAYS  viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: D. oo im  ix. Estimated depth of infiltration around spill point: 2.50 im  Estimated Volume of infiltrated oil at spill point: Vinf a: barrels
1.26
2. Estimated Volume of infiltrated oil at second spill point [if applicable] (Vinf b)
i. Area* (m²) of soil covered by the oil:
ii. Average Depth (n) above leaking facility i.e. pipeline/flowline:
iii. Soil type: iv. Pe (effective porchity of the soil)
v. Cause of spill: vi. Oil type
vii. Oil Residence time on site, day:
viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline:
ix. Estimated depth of infiltration around spill point:
Estimated Volume of infiltrated oil at spill point. V <sub>inf_b</sub> : barrels

3. Estimated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)

i. <i>i</i>	Area (m2) of soil	covered by the oil	ŀ	20,405	
			oil in touch with s		<del>.</del>
	•	•			- o l
			urface of infiltrati	on or on:	00 lm
	Soil type:CL	•	00		
v.	P <sub>e</sub> (effective poro	<u>-</u>			
,	vi. Estima	ted Volume of inf	iltrated oil. At V	iof: <b>8</b> -	48 barrels
23. Computation	of estimated vo	lume of oil on o	open water based	d on standard colo	ration.
•	of oil on open wa	- 1			
	verage depth of o		on coloration (	**Spill Factors fro Edition)	m USCG FOG (2000
	Thickness	Percentage		,	
D 1 37 14 1	(mm)	coverage	Volume (m3)	٦	
Barely Visible	0.00004			1	
Silvery Slight Color	0.00008	-	<del></del>	1	
Bright Color	0.00013	<u>~10+</u>	, alt	7	
Duli Duli	0.001	1-1-	ICABLE	1	
Dark	0.002	100	χ	1	
Black oil	0.1			1	
Emulsian (200/ Oil)				1	
Emulsion (30% Oil)		100%			
iii. 「	Percent Total Estimated Volu	100% me of oil on open	water. V <sub>wat</sub> :	\$ 1.1	Barrels
24. Calculation	<u></u>			NIL_	
	actor: 15%	vailable for eva		surface area: <u>90</u>	8-95 BARA
- Cuar	acction Eastern	(E Factor) for S	DDC Crudo oil		
Oil Type	Days on site	Bonny Light	Bonny Me	dium	
Oil Residence time	< 1 day	10%		5%	
	1-7 days	25%		15%	
	>7 days	40%		25%	
25. Net Estima	ted Spilled Vol	ume V <sub>va</sub> (hhle)	= V <sub>****</sub> (bhls) +	$V_{\text{wat}}$ (bbls) + $V_{\text{i}}$	or (bbls) + V
$\frac{\text{(bbis)} + V_{\text{rec}}}{\text{(bbis)}}$	$\frac{1}{2} \frac{\partial u}{\partial x} = \frac{1}{2} \frac{\partial u}{\partial x}$	LL A Ku	L QQQ.	21+ 9.74	+ Nisi

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED.
JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1005316 JIV report S/N: 0090
Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m³ to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number use the following rules:
Any spill volume in excess of 1 bbl is rounded up to the next whole number.
<ul> <li>Any spill volume in less than I bbl is rounded up to the next 0.1 bbl.</li> </ul>
Examples: Calculated volume = 15.3 bbl Reported volume = 16 bbl Calculated volume = 0.35 bbl Reported volume = 0.4 bbl
Calculated volume = 0.01 bbl Reported volume = 0.1 bbl.
Whetever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the HV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the HV report.
26. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact after the initi response and therefore recommend that the site be closed out.
B. Investigation of the incident site showed that there is residual impact on site requiring furth works
27. REPRESENTATIVES  This report was filled, agreed and signed on the 12/57/2013 by joint investigation representatives from  • Host Community: □  • Department of Petroleum Resources [DPR]: □
National Oil Spill Detection and Response Agency [NOSDRA]:       The state of

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1005316 JIV report S/N: 0090

28. Appendix 1: Overview sketch of the site

