


Overview: Part of spill impact on 2" BNAG-Incoming Manifold Condensate Line at Bonny. Picture was taken during Joint Investigation of 28th June 2018.



Close-up: Corrosion on 2" BNAG-Incoming Manifold Condensate Line at Bonny. Picture was taken during Joint Investigation of 28th June 2018.