



Overview: Extent of the spill incident impact on 8" Obigbo-North Pipeline at Obigbo .
Pictures taken during Joint Investigation of 25th March, 2011



Close-up: Spill was due to illegally welded point on 8" Obigbo-North Pipeline at Obigbo.
Picture taken during Joint Investigation of 25th March, 2011.