



Close-up: Spill due to corrosion on Cawthorne Channel2 Well51T flowline at Mbiama.
Picture taken during Joint Investigation of 17th October, 2011.