



Overview: Part of spill impact on 8" Isimiri Imo River gate Delivery line at Umuelechi
 Picture was taken during Joint Investigation on 13th September 2020.



Close-up: 2" Failed ball valve installed at 12 o'clock position on 8" Isimiri Imo River gate Delivery line at Umuelechi. Picture was taken during Joint Investigation on 13th September 2020.