Overview: Part of spill impact on 36'' Rumuekpe - Nkpoku Pipeline Right of Way at Ogbodo-Isiokpo. Picture was taken during Joint Investigation of 24th December 2018.



Close-up: Leaking Illegal Fitting on 36'' Rumuekpe - Nkpoku Pipeline at Ogbodo-Isiokpo. Picture was taken during Joint Investigation of 24th December 2018.