30111 INVESTIGATION REPO	ORT FOR INCIDENT NO	D: <u>0115 104451</u>
(Note: As practicable as possible the JIT r	eport is to be signed in the	field by all the participating parties)
A. GENERAL INFORMATION:		. 61
1. Spill incident Number: 7044	51 2.Type	of incident* GPL SPILL
3. Name of Location 10" EKYLAM	· -	
		WERC 6. LGA AKUKU - TORU
7. Type of Production facility/Installation _	· · · · · · · · · · · · · · · · · · ·	
B. INCIDENT INFORMATION:	·	TOOL CAMPINDISTIFE AND A CAMPING
9. Details of incident a. Date of incident: 23th Augus b. Date/Period of investigation: 28	· · · · · · · · · · · · · · · · · · ·	
c. Description of spill point environments		KA' SEP(RMBER, 2011
☐ Firmed soil	Loose soil	☐ Previously excavated area
Under water	Swampy	☐ Exposed pipe surface
☐ Well Platform (on Water)	4 	
d. Description of leak point (tick as a	pplicable):	□ Rig
☐ Drilled hole	☐ Hack saw cut	☐ Explosive tear,
□ Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap v	•	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkerin	•	☐ Third party tampering with Clamp
☐ Third party tampering with valve	· ·	☐ Third party tampering with flange,
External Corrosion	, south 15,	☐ Internal Corrosion
☐ Saver-pit over flow,	☐ Surge vessel overflow	
☐ Flare System/Bund wall Failure		
Cold vent	☐ Relief valve failure	□ com unit failure
.*	in Renet valve failure	☐ Others (specify)
e. Incident due to:	,	
☐ Third party interference	☐ Operational	□ Others (specify
f. Spill point coordinates Measuring unit measuring	(MINNA MID-E	2 cu T. \.
Northing:		Easting:
56154.59MN		169523.00mE.

Page 1 of 9

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO. 0115 704451 JOINT INVESTIGATION REPORT FOR INCIDENT NO: C. RISK ASSESSMENT 10. Type of environment: Swamp □ Land □ Water ☐ Seasonal swamp Type of environment to which oil has spread: ☐ Land □ Water ☐ River (identify)_ ii. Weather condition Sunny □ Raining 11. Distance from the nearest sensitive habitat Government reserved and designated protected area ,m] ☐ Drinking water source ,m] NOT ☐ Built up area ,m] □ Farmlands ,m] ☐ Fish Farm/Pond ,m] ☐ Fishing net lm, □ Others (specify). 12. Containment measures put in place; Booms ☐ Trench □ Dyke Others: NOT APPLICABLE. 13. Any pictures or video coverage? 14. Was there any disruption to the investigation?

If yes give bri	f yes give brief description:							
								
		_		_				

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number		Comments
ļ						
	*1(. =		K O - •	~	1.10.7
	NONEX	1111	7	AKFA	5	MUACI
	7 4 1 - 0			, ~, ,		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0115 70445

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
<u> </u>		- GATTELIA	H A	CA N	= IMA	A
<u> </u>	160110	MILLICI	7 ()	<u>un 01</u>	[10]:	*/~!
L					' '	


17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments	
	North		1001	ADA ET	
-	INDIAM V	MITTIN	KKTA OF T	MPACT	

18. Others (Specify) i.e. Animal Traps

S/N	Others Description		⊉uantity/Size	Comments	
	A (a)	C 5== c	A a b = 1	160 5	
	NOME A	Hiliten 1	YREA OF 1	MIXC (
	, e , , , , , , , , , , , , , , , , , ,				

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)



A. SECTION OF 10" EKULAMA - SAN BARTH PIPELINE OIL SPILL.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0115 704451

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

	MINHA	MID-BEIT
S/N	Northing (METELS)	Easting (METERS)
32	56157-71 m	469518·31m
33	56160 · 68 m	469524-53 m
34	56157·44m	469529 12 m
35	56149-60 m	469529·66 m
30	56148 · 25 m	469521-82m
37	56133 - 11 m	469498-85 m
38	56157 . 49	469473 · 18 m
<u> </u>	•	
	·	

G. INCIDENT INFORMATION:

20.	Impact	ed Ai	ea D	etails
-----	--------	-------	------	--------

•	Total calculated area of impact	0-07Ha
•	Impact within SPDC R.O.W	0.07 Ha
•	Impact outside R.O.W	NIL

21. Volume of oil recovered before completion of JIV (V_{recJ}):

Recovered oil V _{rec,F}	NIL	barrels
----------------------------------	-----	---------

20. Computation of the residual volume on site

a.	Computation of volume of	f pool of free phase	oil (on land o	or confined water	body). Stry ~ 2
	i. Area (m²) o	ccupied by pool of fi	ee phase oil		20 H

ii. Average Depth (m) of pool of free phase oil _______ o.col m

iii. Emulsification factor: NIL

iv.	Volume of pool of	f free phase of	oil. V _{pool} :	02.0	barrels

JOINT INVESTIGATION REPORT FOR INCIDENT NO. 445

- b. Computation of volume of infiltrated oil in the soil (V_{inf}).
 - i. Area (m²) covered by the oil: 200 m²
 - ii. Area of the pool of free phase oil in touch with soil:
 - iii. Average Depth (m) below ground surface of infiltration of oil: 0.02 m
 - iv. Soil type:
 - v. $P_{\rm e}$ (effective porosity of the soil).

iv.	Volume of infiltrated oil. Vinf	0.20	barrels
-----	---------------------------------	------	---------

- 21. Computation of volume of oil on open water based on standard coloration.
 - i. Total area of oil on open water:
 - ii. Table of average depth of oil on water based on coloration *

	Thickness (mm)	Percentage coverage	Volume (m3)	_
Barely Visible	0.00004			<u> </u>
Silvery	0.00008			
Slight Color	0.00015]
Bright Color	0.0003]
Dull	0.001	120	0.0005m3	<u> </u>
Dark	0.002			
Blackoil	0.1		<u> </u>	1
Emulsion (30% Oil)	1			
	Percent Total	100%	Total Volume 6 003	Bl bbl
iii. Volume of oil on open water. Vwat: 0-0031 barrels			barrels	

- 22. Calculation of evaporated volume:
 - i. Oil type: BONNY LIGHT
 - ii. E-Factor: 257

iii. Volume of evaporated oil. V evap:	0-23	barrels
--	------	---------

Evapor	ration Factors (E-Fa	actor) for SPDC Crue	de oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) +$

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 7544

V _{Est} (bbls)= 0.23+0.603(+0.20+0.50=0.93 Breeels.
24. Net Total Estimated Spilled Volume V Est(bbls) = Vevap(bbls) + 0.6*Vwat (bbls) + Vinf (bbls) +
V_{pool} (bbls) + V_{recJ} (bbls)
VEst(bbls)= 0.28+0.00189+0.20+0.50 20.93189 -0.93 BMG

25. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out.
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

26 Signatories

This report was filled and signed on the $\frac{22/69}{20}$ at incident site by joint investigation representatives from

- Host Community
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:

 ✓
- Shell Petroleum Development Company [SPDC]:□

Tick as applicable

^{*}Calculation of the respective estimated volume is to be done using the new spill estimation software on site

^{*}Conversion of m3 to barrels is Total volume VT (m3) x 6.29

^{*}Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0115 754451

20. Appendix 1: Overview sketch of the site

Location: 10" EKULAMA - BAN BARTH PIPELINE AT SAN BARTH LUCKYLAND SAM BARTH KIMINFOLD. 4mm Chrosian Hole 47 7:20 ° Chack POSITION ON LO" EXECUTADO - SAN BROTH Boom Steran. SHEEM IN OPEN WITH LIGHTH IMPACT. WATER. NOT RECOVERABLE

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 784451 0115

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

(MINNA MOD - BETT)

	(MINIA MID -	- BE(T)
S/N	Northing Market	Easting me722s
		+/
_		
·		
		·
		-