JOINT INVESTIGATION REPORT FOR INCIDENT NO: ... 0002 700723

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:			
1. Spill incident Number:	<b>723</b> 2.Type o	of incident* OIL SPI	LL_
3. Name of Location 8" OBIG	BO NORTH - 1	NEW ELELENWO	PIPELINE
4. Name of nearest community AKPA	105. State: RIV	ERS 6. LGA FLE	ME
7. Type of Production facility/Installation			
B. INCIDENT INFORMATION:			,
D. Details of incident a. Date of incident: 16TH			
b. Date/Period of investigation:	ITH AUGUST,	_2011	
c. Description of spill point environ	ment		
Firmed soil	□ Loose soil	☐ Previously excavated are	a
☐ Under water	□ Swampy	☐ Exposed pipe surface	
☐ Well Platform (on Water)		□ Rig	
d. Description of leak point (tick as			
□ Drilled hole	☐ Hack saw cut	☐ Explosive tear,	
□ Complete Rupture	☐ Inward dent,	☐ Well head tampering	
☐ Failed Weld-on illegal hot tap		☐ Missing Pipeline/Flowlin	e)
☐ Crude oil theft (illegal bunkeri		☐ Third party tampering with	th Clamp
☐ Third party tampering with val	ve setting,	☐ Third party tampering with	th flange,
☐ External Corrosion		Internal Corrosion	
☐ Saver-pit over flow,	☐ Surge vessel overflow,	Outward dent	
☐ Flare System/Bund wall Failur	e □ Valve Failure	com unit failure	•
□ Cold vent	☐ Relief valve failure	☐ Others (specify) NoT	APPLICABLE
e. Incident due to:	_		
☐ Third party interference	<b>✓</b> Operational	□ Others (specify No	T_APPLICABLE
	INNA MID-BELT	)	
Measuring unit M Northing:		Easting:	
		_	İ
94033.87		516801.24	
·			
		· — — — — — — — — — — — — — — — — — — —	

Page 1 of 9

<sup>\*</sup>This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0002 700 723

C. RISK AS	SSESSME	NT						
10.	Type	of environment:						
Ø	Land	□ Swamp	☐ Water	□ Sea:	sonal sw	amp		
i	. Type o	of environment to	which oil has spr	ead:			• .	
A	Land	□ Swamp	☐ Water	□ Rive	er (identi	fy) NOT	APPLIC	ABLE
ii.	Weath	er condition						
	Raining ance from t	□Sunny the nearest sensiti	ve habitat		,			
00000	Drinking w Built up are Farmlands Fish Farm/ Fishing net Others (spe	Pond	APPLICAB		[ [ [ [	,m] ,m] ,m] ,m] ,m]		
	Booms	Trench	□ Dyke					
. 🗖	Others:	NoT AF	PLICABLE				·	
13. Any	pictures or	video coverage?			[Y] <b>/</b>	[N]		
14. Was	there any d	disruption to the in	nvestigation?		[Y]	[N]		
If yes give bri	ief descripti	ion:	<b>F</b>	<del> </del> P	PL	10	AB	LE

### D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

#### 15. Structures / Properties

S/N Type	of Structures	Description	Size	Number	Comments
NO	NEV	H	N A	REA OF	IMPACT

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 10072

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
1	ONI	18/1-71		0 T X X	\ <del>+</del>	710
	DIVE	<del>-                                    </del>	NA	KEAC		PACI

17. Fish/Nets/Ponds


S/N	Fish/Nets/P	onds	Description		Quantity/Size	Comments
4				۸		4
		14 4	1111	$\Lambda D \Pi$	) ht	MADNOT
INC		MLI	MIN	MNI		
	. ,	, 4, 6				

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description		Quantity/Size	Comments
	1		4		
$\Box \Delta \Box \Delta$		X III Talana	APT	X nt	LOVOT
	$N \times V$	VIII HIN	ANE	AUT	MLHC
		* * 4 * * * *	,		

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

SECTION OF 8" OBIGBO NORTH - NEW ELELENWO PIPELINE AT AKPAJO SHOWING POSITION OF CORROSION TEAR.



JOINT INVESTIGATION REPORT FOR INCIDENT NO. 10123

#### F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2) (MINNA MID-BELT)

S/N	Northing (M)	Easting (M)
193	94040.03	516795.09
194	94024.66	516798.14
196	94027-70	516816-63
197	94630.75	516825.88
198	94033.81	516832.05
199	94039.84	516887.53
200	94052-13	516884.47
203	94049.17	516856.73
204	94052.19	516853.66
205	94049.14	516847.49

#### **G. INCIDENT INFORMATION:**

20.	Impacted	l Area	Detail	S

Total calculated area of impact	0.1254 Ha	_
Impact within SPDC R.O.W	0.1120 Ha	_
Impact outside R.O.W	0-0134 Ha	_
21. Volume of oil recovered before completion of J	IIV (V <sub>rec.j</sub> ):	
Recovered oil V	rec.F. NIL	barrels
20. Computation of the residual volume on site		
<ul> <li>a. Computation of volume of pool of free phase oil (on</li> <li>i. Area (m²) occupied by pool of free phase</li> </ul>		·
ii. Average Depth (m) of pool of free pha	ase oil	_
iii. Emulsification factor:		
iv. Volume of pool of free phase	e oil. V <sub>pool</sub> : 20.51	barrels

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 700 723

- b. Computation of volume of infiltrated oil in the soil (V<sub>inf</sub>).

  - ii. Area of the pool of free phase oil in touch with soil: (m²) NIL
  - iii. Average Depth (m) below ground surface of infiltration of oil: 0.015
  - iv. Soil type: CLAY
  - v.  $P_{e}$  (effective porosity of the soil).

iv. Volume of infiltrated oil. V<sub>inf</sub> 3.31

- 21. Computation of volume of oil on open water based on standard coloration.
  - i. Total area of oil on open water:
  - ii. Table of average depth of oil on water based on coloration \*

	Thickness (mm)	Percentage coverage	Volume (m3)		
Barely Visible	0.00004				
Silvery	0.00008				
Slight Color	0.00015	170	1		
Bright Color	0.0003				
Dull	0.001	ADDITE	A O I F		
Dark	0.002	APPIL	ABLE		
Black oil	0.1	711 1			
Emulsion (30% Oil)	1	·			
,	Percent Total	100%	Total Volume	NIL	bbl
[K]	iii. Volume of o	l on open water. V <sub>wat</sub> :	NIL	barr	rels

- 22. Calculation of evaporated volume:
  - i. Oil type: BONNY MEDIUM
  - ii. E-Factor: 5%

iii. Volume of evaporated oil. V evap:	4-2	barrels

Evapor	ration Factors (E-Fa	actor) for SPDC Crue	de oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
<u> </u>	1-7 days	25%	15%
	> 7 days	40%	25%


23. Gross Total Estimated Spilled Volume  $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) = 4.2 + NiL + 3.31 + 20.51 + NiL = 28.02$ 

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0002 700 723

V <sub>Est</sub> (bbls)= 28.02 BARRELS			
24. Net Total Estimated Spilled Volume V Est(bbls) = Vevap(bbls) + 0.6*Vwat (bbls) + Vinf (bbls) +			
$V_{pool}$ (bbls) + $V_{recJ}$ (bbls) = 4.2 + NIL+ 3.31+ 20.51+ NIL = 28.02			
VEst(bbls)= 28.BARRELS			
*Calculation of the respective estimated volume is to be done using the new spill estimation software on site *Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil.			
25. GENERAL STATUS OF THE SITE			
A. Joint investigation of the incident site found that there is no residual impact. After the			
initial response and therefore recommend that the site be closed out			
B. Investigation of the incident site showed that there is residual impact on site requiring			
further works			
26 Signatories			
This report was filled and signed on the investigation representatives from			
Host Community			
• Department of Petroleum Resources [DPR]: 🖳			
National Oil Spill Detection and Response Agency [NOSDRA]:			
State Ministry of Environment [SME]:			
Nigeria Police Force [NPF]:□			
Shell Petroleum Development Company [SPDC]:			
Tick as applicable			

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 100 723

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 700 723

# 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
		+
		. /
	+/	
-		