THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 1. Spill incident Number: 675228 2. Type of incident* SPILL 3. Name of Location 14" OKOROM - RUMU EKPE PRELINE 1. Spill incident Number: 4. Name of nearest community | KARAMA 5. State: BAYELSA 6. LGA YENAGOA 7. Type of Production facility/Installation OTL PIPELINE 8. Asset owner/District NESP/L **B. INCIDENT INFORMATION:** 9. Details of incident a. Date of incident: b. Date/Period of investigation: c. Description of spill point environment Loose soil ☐ Firmed soil Previously excavated area ☐ Under water □ Swampy ☐ Exposed pipe surface ☐ Well Platform (on Water) □ Rig d. Description of leak point (tick as applicable); ☐ Drilled hole Hack saw cut ☐ Explosive tear, ☐ Complete Rupture □ Inward dent, □ Well head tampering □ Failed Weld-on illegal hot tap valve, ☐ Missing Pipeline/Flowline) □ Crude oil theft (illegal bunkering) point, ☐ Third party tampering with Clamp ☐ Third party tampering with valve setting. ☐ Third party tampering with flange, □ External Corrosion □ Internal Corrosion □ Saver-pit over flow. ☐ Surge vessel overflow, ☐ Outward dent ☐ Flare System/Bund wall Failure ☐ Valve Failure □ com unit failure □ Cold vent ☐ Relief valve failure □ Others (specify) e. Incident due to: Third party interference ☐ Operational □ Others (specify_ f. Spill point coordinates Measuring unit Northing: 445 416.29 125 79B · (H

Page 1 of 9

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0010 695228 (D)

C. RISK ASS	ESSMEN	NT		•
10.	Туре	of environment:		
▽ La	nd	□ Swamp	Water	☐ Seasonal swamp
i.	Type of	f environment to w	hich oil has sprea	ad:
♥ La	nd	☐ Swamp	₩ater	□ River (identify)
ii.	Weathe	r condition		
□ Rai 11. Distand		Sunny ne nearest sensitive	e habitat	
□ Dr □ Bu □ Fa □ Fi: □ Fi: □ Ot	rinking wanilt up area rmlands sh Farm/P shing net hers (spec	ond		area [NML ,m] [NML ,m] [NML ,m] [NML ,m] [> 100 ,m] [NML ,m] [NML ,m]
□ Во	oms	□ Trench	□ Dyke	
□ Ot	hers: /	HTURAL	DEPRES	SION
13. Any pi	ctures or	video coverage?		[X] [N]
14. Was th	ere any di	isruption to the inv	vestigation?	[Y] [V]
If yes give brief	description	on:		
NO	T	APP	'H CA	FBLE

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	NONE	MITH	HA	AREA	OF IMPACT
					11111111

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0010 695 228 (D)

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	PALMTERES			V	Fwe	
		-				

17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description		Quan	tity/Size	Comments
	No.	I I COT LL DI	Λ./		~~~ · ·	000
	HWW E	+ Mr. HANA	M	WA.	07-11	NFACT
		_				

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	NONE	WITH M	AREA NE	TOPACT
	1,0110		11107.01	'

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

4 SECTION	70	14	OKORDIA - RUMUEKAE	PUELME	SHOWING
		•	0° Clock Position		



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0010 67522 8 (D)

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

		· · · · · · · · · · · · · · · · · · ·
S/N	Northing	Easting
1	125804.13	445 410 · 15
٦	125797.99	445 407 - 05
3	125797-94	445 422. 45
4	125788.74	445 416 · 26
5	125776.44	445 419. 31
6	125 797. 92	445 428.62
7	125831-69	445 466.85
8	125 951. 14	445 551.26
9	125 932. 39	445608.05
10	125836-40	445 518 · 13
//	125740.53	445 464.33
/2	125741. 23	445 450 · Sf
/3	125677.88	445 413 57

G. INCIDENT INFORMATION:

20	Im	nact	ted	Area	Details

ImpImp	pact within SPDC R.O.W pact outside R.O.W oil recovered before completion of JIV (V _{rec.J}):	
	Recovered oil V _{rec.J} . Mu_	barrels
	on of the residual volume on site	
a. Computation i.	n of volume of pool of free phase oil (on land or confined water body). Area (m²) occupied by pool of free phase oil	
ii.	Average Depth (m) of pool of free phase oil	
iii.	Emulsification factor:	
;	iv. Volume of pool of free phase oil. V _{pool} : 52.2	barrels

		VELOPMENT COMI			_	
		rated oil in the soil (V_{inf}) .	- 001			
o. Computation t		· ····/	COE			
	i. Area (m²) covered by the oil: 15185					
i	i. Area of the poo	ol of free phase oil in tou	ch with soil:_	922		
ii	 Average Depth 	n (m) below ground surface	ce of infiltration	on of oil: () 'VVIS	<u> </u>	
iv	v. Soil type: (2LM	$\circ \omega$			
•	v. $P_{\rm e}$ (effective p	orosity of the soil)	8%			
iv	v. Volume o	f infiltrated oil. V _{inf}	/2,-	2BARREL	barrels	
i. Total area o	of oil on open wate erage depth of oil Thickness (mm)	on open water based of cr:	on *	oloration. ume (m3)	1	
Barely Visible	0.00004	A 15-5				
Silvery	0.00008	 NO 1-				
Slight Color Bright Color		7 7	-			
Dright Color Dull	0.0003	1-001	AB	LE		
Dark		- THE	+ +]	
Black oil	0.1					
Emulsion (30% Oil)	1				J	
	Percent Total	100	0% Total	Volume NW_	bbl	
Γ	iii. Volume of o	il on open water. Vwat	NU		barreis	
22. Calculation of	of evaporated vol	lume:				
		Y WEDISM		•		
	actor: 25	Jo				
i	ii. Volume of ev	raporated oil. V evap:	21.9	5	barrels	

Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil	< 1 day	10%	5%
him	1-7 days	25%	15%
	> 7 days	40%	25%

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) = 21.5 + NLL + 12.2 + 52.2 + NLL = 85.9$

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0010 69528 (D)

VER(bbis)= 85.9 BARRELS
24. Net Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + V_{inf}(bbls)$
Vpool (bbls) + Vrecj (bbls) = 21-5+ NUL+ 12-2+52-2+ MU = 85-9
VEst(bbis)= 85.9 BALLELS
*Calculation of the respective estimated volume is to be done using the new spill estimation software on site

25. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact After the initial response and therefore recommend that the site be closed out B. Investigation of the incident site showed that there is residual impact on site requiring further works

26 Signatories

12/08/2011 at incident site by joint This report was filled and signed on the investigation representatives from

- Host Community ✓
- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
 ✓
- Shell Petroleum Development Company [SPDC]:
 ✓


Tick as applicable

^{*}Conversion of m3 to barrels is Total volume VT (m3) x 6.29

^{*}Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0010695228(D)

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0010 695228(D)

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
14	125695.02	445356.06
7		
4		