

<u>Close-up:</u> Spill due to hacksaw cut on 14in Okordia-Rumuekpe pipeline at Ikarama. Picture taken during Joint Investigation of 9th August, 2011.

1