



Overview: Extent of the spill incident impact at Egwa I Well 27 location at Okpogbene, showing attached third party hoses . Picture was taken during incident confirmation flight of 28<sup>th</sup> January 2011



Close-up: Image showing third party connection on Egwa I Well 27 well head at Okpogbene. Picture was taken during JIV of 1<sup>st</sup> February 2011