



Overview: Extent of the spill incident impact on 10" Kokori Pipeline route at Idjerhe.
Picture was taken during JIV of 11 January 2011



Close-up: Leak from a hole on 10" Kokori Pipeline . Picture was taken during JIV of
11 January 2011