



Close-up: Illegal fittings on 12" ImoRiver-Ogale pipeline at Owaza. Picture was taken during Joint Investigation of 27th November, 2011.