JOINT INVESTIGATION REPORT FOR INCIDENT NO:

0061 435234

(Note: As practicable as possible the JIT rep	ort is to be signed in the fi	ield by all the participating parties)
A. GENERAL INFORMATION:		
1. Spill incident Number: 73523	34 2.Type of	fincident* OIL SPILL
3. Name of Location 24" TRAT	VS - RAMOS	PIPELINE @ AGHORO
4. Name of nearest community AGHER	0-2 5. State: BAY	ELSA 6. LGA EKEREMER
7. Type of Production facility/Installation	PUNK LINE 8. A.	sset owner/District PIPE LINE
B. INCIDENT INFORMATION:		
9. Details of incident a. Date of incident: 28/10 b. Date/Period of investigation: 03	2011	1223 HR
c. Description of spill point environme		
☐ Firmed soil	□ Loose soil	J Previously excavated area
□ Under water	□ Swampy	☐ Exposed pipe surface
☐ Well Platform (on Water) d. Description of leak point (tick as ap	plicable);	□ Rig
☐ Drilled hole	☐ Hack saw cut	□ Explosive tear,
☐ Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap va	alve,	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkering	g) point,	☐ Third party tampering with Clamp
☐ Third party tampering with valve	e setting,	☐ Third party tampering with flange,
□ External Corrosion		☐ Internal Corrosion
☐ Saver-pit over flow,	□ Surge vessel overflow	, 🗖 Outward dent
☐ Flare System/Bund wall Failure	□ Valve Failure	com unit failure
□ Cold vent	☐ Relief valve failure	☐ Others (specify)
e. Incident due to:		_
☐ Third party interference	☐ Operational	MOthers (specify MYSTERY (CRUDE OIL IMPACT OF WHESTABLISHED SOURCE
f. Spill point coordinates		
Measuring unit		
Northing:		Easting:
	}	
	}	

Page 1 of 9

100

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0061 735234

C. F	RISK ASSESSMEN	IT.						
	10. Type o	of environment:						
	☑ Land	⊠Swamp	□W	⁄ater □	l Seasonal swa	mp	,	
	i. Type of	environment to	which o	il has spread:				
	⊾Land	□ Swamp	WW	[/] ater □	River (identif	ỳ)		
	ii. Weathe	r condition						
1	☐ Raining 11. Distance from th	☑Sunny ne nearest sensiti	ve habita	at				
☐ Government reserved and designated protected area ☐ Drinking water source ☐ Built up area ☐ Farmlands ☐ Fish Farm/Pond ☐ Fishing net ☐ Others (specify). 12. Containment measures put in place; ☐ Booms ☐ Trench ☐ Dyke					a [HL [ML [ML [ML	,m] ,m] ,m] ,m] ,m]		
	13. Any pictures or	video coverage?) <u> </u>	[X]	[N]		
	14. Was there any d	isruption to the i	nvestiga	ition?	[Y]	[W]		
If ye	s give brief descripti							
	NOT	APPL	CAR	LE				
	D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL 15. Structures / Properties							
S/N	Type of Structu	res Descr	iption	Size	Number		Comments	

S/N	Type of Structures	Description	Size	Number	Comments
<u> </u>					
	NONE WI	THIN	ADFA	NC	IMPART
	Viana Mi	111119	NI CH	UF	11317916
-					

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0061 735234 JOINT INVESTIGATION REPORT FOR INCIDENT NO:____

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	MANGROVE	755	755		LOT_	
		\		\		

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments	
	NONE WITH	APEA C	FIMPACT		

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	gantity/Size	Comments
	MONE	WITHIN AREA	OF IMPACT	
·				

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0061 735234

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
	124671	332394
	124 669	332391
	124672	332387
	124 674	332390
	124666	332398
	124665	332402
	124 653	332386
	124651	332 386
	124647	332387
	124 645	332 384
	124 637	332374
	124 633	332377
	124 647	332358

G. INCIDENT INFORMATION:

20	Impacted	Area	Detai	1c
4 0.	minacicu	лиса	Duai	1.5

	• Tot	al calculated area of impact 384 M ²					
		pact within SPDC R.O.W 7-8 m^2					
	• Im	pact outside R.O.W 306 M ²					
21.	Volume of	oil recovered before completion of JIV (V _{recJ}):					
		Recovered oil V _{rec.F} .	1L	barrels			
20.	Computation	on of the residual volume on site					
a.		of volume of pool of free phase oil (on land or confined Area (m²) occupied by pool of free phase oil					
	115T 4001114Q1E						
	iii.	ii. Average Depth (m) of pool of free phase oil Not Applicable iii. Emulsification factor: NOT Applicable					
		iv. Volume of pool of free phase oil. V_{pool} :	NIL	barrels			

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 006! 735234

b.	Computation	of volume	of infiltrated	oil i	n the s	oil (V	V_{inf}	١,
----	-------------	-----------	----------------	-------	---------	--------	-----------	----

i. Area (m^2) covered by the oil: 107 M^2

ii. Area of the pool of free phase oil in touch with soil: N1

iii. Average Depth (m) below ground surface of infiltration of oil: 0.02 M

iv. Soil type: _ CLAY

v. $P_{\rm c}$ (effective porosity of the soil).

iv. Volume of infiltrated oil. V_{inf} | . O 8 | barrels

21. Computation of volume of oil on open water based on standard coloration.

i. Total area of oil on open water: 277 m

ii. Table of average depth of oil on water based on coloration *

	Thickness (mm)	Percentage coverage	Volume (m3)	
Barely Visible	0.00004	50 Yz	0.00000554	
Silvery	0.00008	15 %	0.000003324	
Slight Color	0.00015	10 %	0.00004155	
Bright Color	0.0003			
Dull	0.001			
Dark	0.002			
Black oil	0.1	25 %	0.006925	
Emulsion (30% Oil)	1			
	Percent Total	100%	Total Volume 0 0	[86]
	iii. Volume of oi	I on open water. Vwat:	0.04 b	arrels

22. Calculation of evaporated volume:

i. Oil type: Berny MEDIUM

ii. E-Factor: 15 %

iii.	Volume of evaporated oil. V evap:	0.70	barrels
l	•		

Evaporation Factors (E-Factor) for SPDC Crude oil				
Oil Type	Days on site	Bonny Light	Bonny Medium	
Period Since Oil Spill	< 1 day	10%	5%	
	1-7 days	25%	15%	
	> 7 days	40%	25%	


23. <u>Gross Total Estimated Spilled Volume</u> $V_{Est}(bbls) = V_{cvap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$

JOINT INVESTIGATION REPORT FOR INCIDENT NO: $V_{Est}(bbls)=$.32 BBLs 24. Net Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) +$ V_{pool} (bbls) + V_{recJ} (bbls) VEst(bbls)= 1.30 BBLS *Calculation of the respective estimated volume is to be done using the new spill estimation software on site *Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE A. Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out B. Investigation of the incident site showed that there is residual impact on site requiring further works 26 Signatories 03/11/2011 at incident site by joint This report was filled and signed on the investigation representatives from Host Community □ Department of Petroleum Resources [DPR]: □ National Oil Spill Detection and Response Agency [NOSDRA]: State Ministry of Environment [SME]: □ Nigeria Police Force [NPF]:□ • Shell Petroleum Development Company [SPDC]:☑

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0061 735234

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
	124680	332382
	124 686	332378
		332383
	124691	332389
-		