JOINT INVESTIGATION REPOR	RT FOR INCIDENT NO:	0166 741104
(Note: As practicable as possible the JIT rep	ort is to be signed in the fi	eld by all the participating parties)
A. GENERAL INFORMATION:	·	
1. Spill incident Number: 74116	2.Type of	incident* Ol SPILL
3. Name of Location KRAKAMA	WELL 13	
4. Name of nearest community BILL F	5. State: R V	ERS 6. LGA DEGEMA
7. Type of Production facility/Installation	WELLHEAD 8. As	set owner/District NESI CAWTHORNEL
B. INCIDENT INFORMATION:		•
9. Details of incident a. Date of incident: 4TH b. Date/Period of investigation: 28	NOVEMBER, TH NOVEMB	-2011. ER, 2011.
c. Description of spill point environme	ent	
☐ Firmed soil	□ Loose soil	☐ Previously excavated area
☐ Under water	□ Swampy	☐ Exposed pipe surface
Well Platform (on Water)		□ Rig
d. Description of leak point (tick as ap	•	· · · · · · · · · · · · · · · · · · ·
•	☐ Hack saw cut	☐ Explosive tear,
	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap va	•	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkering	•	☐ Third party tampering with Clamp
☐ Third party tampering with valve	e setting,	☐ Third party tampering with flange,
External Corrosion		☐ Internal Corrosion
□ Saver-pit over flow,	☐ Surge vessel overflow,	
☐ Flare System/Bund wall Failure		com unit failure
□ Cold vent	□ Relief valve failure	DOTHERS (specify) STRUCTURAL FAILURE DUE TO WELL HEAD SUBSIDENCE.
e. Incident due to:		
☐ Third party interference	Operational	□ Others (specify NOT APPLICABLE
f. Spill point coordinates Measuring unit M Northing: 59664,89m	MINNA MA	D BELT asting: H94977. 18m

Page 1 of 9

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 741104

C.	RISK ASSE	ESSMEN	IΤ					
	10.	Type o	of environment:					
	□ Lar	ad	□ Swamp	Water	□ Seasonal	swamp		
	i.	Type of	environment to	which oil has sp	read:			
	□ Lar	nd	□ Swamp	Water	☐ River (ide	entify)		
	ii.	Weather	condition				-	
	☐ Rain 11. Distanc		Sunny e nearest sensiti	ve habitat				
	Government reserved and designated protected area Drinking water source Built up area Farmlands Fish Farm/Pond Fishing net Others (specify). Not APPLICABLE 12. Containment measures put in place;							
	Boo	oms	☐ Trench	□ Dyke				
	□ Oth	ers:	NOT A	HPPLI CABL	Ε			
	13. Any pic	tures or v	rideo coverage?		[Y	[N]		
	14. Was the	ere any di	sruption to the i	nvestigation?	[Y]	[N]		
If y	es give brief	descriptio	n:	X				
				APF	7110	ARIF		
					<u> </u>			

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	* .				
	1	 			
+	ANTE V	HITTH	N. 1	No Fa	
	 	V + I + I		/ 	FIMPACT
	10110	 	 	/ 	/

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0166 741104

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
 	~	\1	•	<u>-</u>		
T	OVE	MITIL	1 4	EA (E IL	DACT
1	0140	AALILIII	1 11	ノレハー	וילוו י דע	MOL

17. Fish/Nets/Ponds

S/N	Fish/Nets	/Ponds	Descript	Description		ize	Comments	
No	NE	WiT	HIN	AREA	OF	1	1PACT	

18. Others (Specify) i.e. Animal Traps

S/N	Others		Description		Quantity/Size		Comments	
M	NF.	A	ATHIN	AR	FΑ	0F	MPACT	
				-			11 11 1 1 - 1 - 1 - 1	

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix1)

LEAK POINT

AS A RESULT OF

STRUCTURAL FAILURE

Page 3 of 9

REA OF



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0166 74104

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

		MINNA	MID	BELT	
S/N	Northing (M)		Easting	(M)	,
1	59666.	40m	494	975.40	
2	59667.	31m	494	077.64	•
3	59666	. 28m		980, 15m	· · ·
4	59663.	40m		1980.06m	
5	59661.	_	,	977.81m	
5	59662.	15m		974.53m	
7	59664.	67m		1973,13m	
_					
					: " -
		,			
			•	·	

G. INCIDENT INFORMATION:

	• Tot	tal calcula	ted area of i	mpact		28 m			
	• Im	pact withi	n SPDC R.C	D.W					
	• Im	pact outsi	de R.O.W					_	
21.	Volume of	<u>oil recov</u>	ered before	completion c	of JIV (V _{rec.J)}	:			
				Recovered oi	l V _{rec.J} :	14	(GROSS)	barrel	s
20.	Computation	on of the	residual vo	lume on site		,			
a.				free phase oil oy pool of free p		onfined water	body).	_	
	ii,	Average	Depth (m)	of pool of free p	ohase oil		.017		
	iii.	Emulsifi	cation factor	:_NIL		•			
		iv.	Volume of	pool of free ph	ase oil. V _{pool}	:	2.99	barrel	s

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0166 741104

b.	Computation of volume of infiltrated oil in the soil (V_{inf}) .	
	_	

1.	Area (m ⁻) covered by the oil:		<u> </u>	_
ii.	Area of the pool of free phase oil in touch with soil:			APPLICABLE
iii.	Average Depth (m) below ground surface of infiltration of oil:) `	10	

iv. Volume of infiltrated oil. V_{init} NIL barrels

21. Computation of volume of oil on open water based on standard coloration.

i. Total area of oil on open water:

ii. Table of average depth of oil on water based on coloration *

	Thickness (mm)	Percentage coverage	Volume (m3)	
Barely Visible	0.00004		:	
Silvery	0.00008	1187	T-	_] .
Slight Color	0.00015			
Bright Color	0.0003		-	
Dull	0.001		-	
Dark	0.002	APPLI	CARIL	
Black oil	0.1	, () (-		
Emulsion (30% Oil)	1			<u></u>
	Percent Total	100%	Total Volume	bbl

iii,	Volume of oil on open water, Vwat	NIL	barrels

22. Calculation of evaporated volume:

i. Oil type: BONNY LIGHT

ii. E-Factor: 40%

iii.	Volume of evaporated oil. V evap:		11. 33	barrels
		 _		

Evaporation Factors (E-Factor) for SPDC Crude oil			
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls) = 11.33 + NiL+ NiL+ 2.99 + 14 = 28.32$

0166 741104 JOINT INVESTIGATION REPORT FOR INCIDENT NO:

$V_{Est}(bbls)=$	28.3 BARRELS
24. Net Tota	Estimated Spilled Volume $V_{Pat}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{int}(bbls)$
V _{pool} (bb	(1.33 + N) + (1.
VEst(bbls)=	22.7 BARRELS

25. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact After the
	initial response and therefore recommend that the site be closed out
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

26 Signatories

28/11 /20 11 at incident site by joint This report was filled and signed on the investigation representatives from . • Host Community • Department of Petroleum Resources [DPR]: ☑ • National Oil Spill Detection and Response Agency [NOSDRA]: • State Ministry of Environment [SME]: □ • Nigeria Police Force [NPF]:□ . Shell Petroleum Development Company [SPDC]: □


Tick as applicable

^{*}Conversion of m3 to barrels is Total volume VT (m3) x 6.29

^{*}Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: U166741104

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 74104 0166

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
	 \ 	
		_
		
	,	
	-	
,		
	<u> </u>	