JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0064 740641

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

	9	, , ,			
A. GENERAL INFORMATION:					
. Spill incident Number: 740641 2. Type of incident* OIL SPILL					
		EMU TRUNKLING @ LYEDG			
. Name of nearest community OG HARD	1-146DE State: DE	CTA 6. LGA ISOKO-NORTH			
7. Type of Production facility/Installation	RUNKLING 8. A	sset owner/District PIPELINE			
3. INCIDENT INFORMATION:					
Details of incident a. Date of incident: 15 11 2	011				
b. Date/Period of investigation: 16	11/2011 @	1350 HRS			
c. Description of spill point environm					
☐ Firmed soil	□ Loose soil	Previously excavated area			
☐ Under water	□ Swampy	☐ Exposed pipe surface			
□ Well Platform (on Water)		□ Rig			
d. Description of leak point (tick as ap	· -				
☐ Drilled hole	☐ Hack saw cut	Explosive tear,			
☐ Complete Rupture	☐ Inward dent,	☐ Well head tampering			
☐ Failed Weld-on illegal hot tap v		☐ Missing Pipeline/Flowline)			
☐ Crude oil theft (illegal bunkerin	-	☐ Third party tampering with Clamp			
☐ Third party tampering with valv	e setting,	☐ Third party tampering with flange,			
☐ External Corrosion		☐ Internal Corrosion			
☐ Saver-pit over flow,	☐ Surge vessel overflow	v, □ Outward dent			
☐ Flare System/Bund wall Failure		com unit failure			
□ Cold vent	☐ Relief valve failure	☐ Others (specify)			
e. Incident due to:					
Third party interference	☐ Operational	☐ Others (specify			
f. Spill point coordinates Measuring unit					
Northing:		Easting:			
1651721	n N	407186 ME			
{					

Page 1 of 9

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0064 7406 41

RISK A	SSESSM	ENT				
10.	Тур	e of environment:				
	Land	□ Swamp	☐ Water	☐ Seasonal swam	p	
	і. Туре	of environment to	which oil has sp	read:		
₽	Land	□ Swamp	☐ Water	☐ River (identify)	
i	i. Wea	ther condition				
☐ Raining ►Sunny 11. Distance from the nearest sensitive habitat						
	Drinking Built up a Farmland Fish Farm Fishing r Others (s	water source area ls n/Pond net pecify).		ַ אָנּג אָנג אָנג	,m] ,m] ,m] ,m]	
	Booms	☐ Trench	□ Dyke			
Ň	Others:_	NATURA	L CONT	4 MMENT		
13. An	y pictures	or video coverage:	•		[N]	
14. Wa	s there an	y disruption to the	investigation?	[Y]	[N]	
es give t	orief descri	ption:				
NOT APPLICABLE						
D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL						
15. Str	ructures /	Properties				
Тур	e of Struc	ctures Descr	ription Size	Number	Comments	
M	ME	Wit	HIM	AREA C	F (mpac	1
	10. 11. Dis 12. Co. 13. An 14. Wa es give t	i. Type Land i. Type Land ii. Wea Raining Raining In Distance from Governm Drinking Built up Farmland Fish Farm Others (s 12. Containment Booms Others: 13. Any pictures 14. Was there any es give brief descri	i. Type of environment to Swamp ii. Weather condition Raining Sunny 11. Distance from the nearest sensite Government reserved and dDrinking water source Built up area Farmlands Fish Farm/Pond Fishing net Others (specify). 12. Containment measures put in place Booms Trench Others: NATURA 13. Any pictures or video coverage? 14. Was there any disruption to the ess give brief description: TYPE/NUMBERS OF PROPERTIONS Type of Structures Description:	10. Type of environment: Stand	10. Type of environment: Nand	10. Type of environment: Stand

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0064 740641

16. Crops/Economic Trees

S/N	Type of crops	Young		Medium	Matured	Quantity	Comments
	PALM TREE		/	- /	YES	5	
	1						
$\Box I$				/			7
		7		T I			

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	POND	NATURAL		
	/			
				F

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	santity/Size	Comments
110	NEW	ITHIN AREA	OF IMPA	c T
_10.5				

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

EXPLOSIVE TEAR
(SPILL POINT)

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0064 740641

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION ·

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
SP	165172	407186
Eu1	165025	407350
· 2	165027	407359
レ3	165042	407356
レ 4	[65 052	407337
v.5	165045	407331
v b	165 0 94	407287
v7	165087	407282
V3	165 175	407195
29	165166	407189
V10	165 188	407177
v11	(65174	407165
EU12	165230	407115

G. INCIDENT INFORMATION:

20.	Im	pacte	ed A	rea l	Deta	ails

Total calculated area of impact	4394 m²	
Impact within SPDC R.O.W	2997 m2	
Impact outside R O.W	1397m2	

21. Volume of oil recovered before completion of JIV (V_{rec}J):

Recovered oil V _{rec.} ;	NIL	barrels

20	Computation	- C 41	المحداد فمست	l'	l	a:+-
/U	t ammulanan	AT THE	recimin	1 1/61	uime on	V114

a.	Computation	n of volume of pool of free phase oil (on land o	r confined wa	ater body).	ALLI
	i.	Area (m ²) occupied by pool of free phase oil _	A10 T	4.00	/VIL
	ii.	Average Depth (m) of pool of free phase oil _	1001	PAPI	CICA BEG

iii.	Emulsification factor: [VO]	AFF LICAG LE
		· ·


	iv. Volume of pool of free phase oil.	V _{pool} :	barrels
--	---------------------------------------	---------------------	---------

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: b. Computation of volume of infiltrated oil in the soil (V_{inf}). i. Area (m^2) covered by the oil: $4394 m^2$ ii. Area of the pool of free phase oil in touch with soil: 1770 m2 iii. Average Depth (m) below ground surface of infiltration of oil: 0.01M iv. Soil type: CLAY v. $P_{\rm e}$ (effective porosity of the soil). Volume of infiltrated oil. Vinf iv.

31.0

barrels

- 21. Computation of volume of oil on open water based on standard coloration.
 - NIL Total area of oil on open water:
 - Table of average depth of oil on water based on coloration *



- 22. Calculation of evaporated volume:
 - Oil type: BONNY MEDIUM
 - E-Factor: 15 % ii.

iii.	Volume of evaporated oil. V _{evap} :	E. T barrels
1111.	volume of evaporated on, v evap.	La pariers
I	F	J - 3 77

Evapor	Evaporation Factors (E-Factor) for SPDC Crude oil				
Oil Type	Days on site	Bonny Light	Bonny Medium		
Period Since Oil Spill	< 1 day	10%	5%		
	1-7 days	25%	15%		
	> 7 days	40%	25%		

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{cvap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_$ V_{pool} (bbls) + V_{recJ} (bbls)


JOINT INVESTIGATION REPORT FOR INCIDENT NO: $V_{Est}(bbls) =$ 36.5 BBLS 24. Net Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) +$ V_{pool} (bbls) + V_{recJ} (bbls) VEst(bbls)= 36.5 BBLs *Calculation of the respective estimated volume is to be done using the new spill estimation software on site *Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE A. Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out B. Investigation of the incident site showed that there is residual impact on site requiring further works 26 Signatories 16/11/2011 at incident site by joint This report was filled and signed on the investigation representatives from Host Community Department of Petroleum Resources [DPR]: □ National Oil Spill Detection and Response Agency [NOSDRA]: State Ministry of Environment [SME]: □ • Nigeria Police Force [NPF]: Shell Petroleum Development Company [SPDC]:□

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO:_

0064 740646

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 740641

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

Northing	Easting
165226	407111
165279	407054
165270	407041
165291	407034
165273	407040
165266	407015
165274	407015
165 267	407023