JOINT INVESTIGATION REPORT FOR INCIDENT NO:	0066	744907
DONAL NATED HOLDING THE OILL FOR MODERAL NO.		, , , , , , , , , , , , , , , , , , ,

(Note: As practicable as possible the J11 rep	port is to be signed in the j	neta by all the participating parties)
A. GENERAL INFORMATION:		
1. Spill incident Number: 7449	0 7 2.Type o	of incident* OIL SPILL
3. Name of Location 8 INCH N	ORTH BANK	K TIG IN MANIFOLD
4. Name of nearest community OBOTC	3. State: DE	LTA 6. LGA BURUTU
7. Type of Production facility/Installation	MAMIFOLD 8. A	sset owner/District PIPELINE
B. INCIDENT INFORMATION:		
9. Details of incident a. Date of incident: 23 11 3	2011	1040HRS
c. Description of spill point environm		
☐ Firmed soil	□ Loose soil	☐ Previously excavated area
☐ Under water	□ Swampy	Exposed pipe surface
☐ Well Platform (on Water)		□ Rig
d. Description of leak point (tick as ap	oplicable);	-
☐ Drilled hole	☐ Hack saw cut	☐ Explosive tear,
☐ Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap va	alve,	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkering	g) point,	☐ Third party tampering with Clamp
☐ Third party tampering with valv	e setting,	☐ Third party tampering with flange,
□ External Corrosion		☐ Internal Corrosion
☐ Saver-pit over flow,	☐ Surge vessel overflow	Outward dent
☐ Flare System/Bund wall Failure	□ Valve Failure	com unit failure
□ Cold vent	☐ Relief valve failure	Others (specify) FAILED BARREDOOR SEAL
e. Incident due to:	_	<u>-</u>
☐ Third party interference	▶ Operational	☐ Others (specify
f. Spill point coordinates Measuring unit		
Northing:		Easting:
155913,	n	321982m
		·

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0066 744907

C.	RISK ASSESSME	ENT			
	10. Type	e of environment:		•>	
	□ Land	□ Swamp	☐ Water	△ Scasonal swamp	
	i. Type	of environment to	which oil has sp	pread:	
	Land	☐ Swamp	☐ Water	□ River (identify)	
	ii. Weath	ner condition			
	☐ Raining 11. Distance from	Sunny the nearest sensiti	ve habitat		
	☐ Governme ☐ Drinking v ☐ Built up ar ☐ Farmlands ☐ Fish Farm ☐ Fishing ne ☐ Others (sp	rea ; /Pond et ecify).		ted area [,m] [,m] [,m] [,m] [,m] , m]	
	Booms	Trench	□ Dyke		
	Others:				
	13. Any pictures o	r video coverage?		[N]	
	14. Was there any	disruption to the i	nvestigation?	[Y] [Y]	
Ify	res give brief descrip	tion:			
	NOT	APF	LICA	BLE	_
D.	TYPE/NUMBERS	OF PROPERTI	ES, IF ANY, FO	OUND WITHIN THE AREA OF SPREAD OF OIL	
	15. Structures / P	roperties			
6/1	J Type of Struct	Dosar Dosar	intion Sizo	Number	_

S/N	Type of Structures	Description	Size	Number	Comments
-		 			
-		17115	1 10	CA AT IN	and T
	NOME W	111910	u AR	en or in	1PAC
		<u> </u>			<u> </u>
L	1	<u>l</u>	<u> </u>	<u> </u>	L

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0066 744907

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
ļ	4 10016	1.14 70014	1 100	-01 -17-	(
	TO THE	WITHIN	ARC	FHOF	IMPAC	- 1
						


17. Fish/Nets/Ponds

S/N	Fish/Nets/Po	onds	Description	on	Quantity/	Size	Comme	nts
	ING	11/1	THIS	ARE	4 OF	IN	DAC	T-
		<i>VV</i> ·	11110	/ (100 /		-,,,		<u> </u>

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	uantity/Size	Comments
	lone v	VITHIM	AREAOF	IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0066744907

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
	155927	321991
	155932	321993
	155927	322008
	155917	322001
	155916	322011
	155911	322012
	155907	322017
	155912	322018
	155899	322020
	155907	322004
	155902	321996
	155901	321990
	155886	321961

G. INCIDENT INFORMATION:

20	Impacted	Aran	Details
20	Impacted	Area	Details

	Total calculated area of impact	
	• Impact within SPDC R.O.W	
	Impact outside R.O.W	
21.	Volume of oil recovered before completion of JIV (V _{rec} J):	
	Recovered oil V _{rec.r.}	barrels
20.	Computation of the residual volume on site	
a.	Computation of volume of pool of free phase oil (on land or confined water body). i. Area (m²) occupied by pool of free phase oil	
	ii. Average Depth (m) of pool of free phase oil NOT APPLICAR	_G
	ii. Average Depth (m) of pool of free phase oil NOT APPLICABI iii. Emulsification factor: NOT APPLICABI	
	iv. Volume of pool of free phase oil. V _{epool} :	barrels

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 0066 JOINT INVESTIGATION REPORT FOR INCIDENT NO: b. Computation of volume of infiltrated oil in the soil (V_{inf}). 1187m i. Area (m²) covered by the oil: ii. Area of the pool of free phase oil in touch with soil: iii. Average Depth (m) below ground surface of infiltration of oil: 0.03 M iv. Soil type: SAND 25% $P_{\rm e}$ (effective porosity of the soil). Volume of infiltrated oil. Vinf iv. 5 7.83 barrels 21. Computation of volume of oil on open water based on standard coloration. NII i. Total area of oil on open water: ii. Table of average depth of oil on water based on coloration * **Thickness** Percentage (mm) coverage MO PROUCES **Barely Visible** 0.00004 Silvery 80000.0 Slight Color 0.00015 Bright Color | 0.0003 Dull 0.001 Dark 0.002 Black oil 0.1 Emulsion (30% Oil) NIL DE Percent Total 100% **Total Volume** iii. Volume of oil on open water. Vwati NIL barrels 22. Calculation of evaporated volume: Oil type: BONNY MEDIUM i. E-Factor: 25% ii. Volume of evaporated oil. V evap: iii. barrels

Evapor	ration Factors (E-Fa	actor) for SPDC Crue	de oil		
Oil Type Days on site Bonny Light Bonny Medium					
Period Since Oil Spill	10%	5%			
	1-7 days	25%	15%		
	> 7 days	40%	25%		

23. Gross Total Estimated Spilled Volum	$\frac{\text{Ne} \ V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + V_{\text{wat}} \ (bbls) + V_{\text{inf}} \ (b$
V_{pool} (bbls) + V_{recJ} (bbls)	


THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0056 744907

Vesi(bbls)= 77-1 BBLs
24. Net Total Estimated Spilled Volume V Est(bbls) = Vevap(bbls) + 0.6*Vwat (bbls) + Vinf (bbls) +
V_{pool} (bbls) + V_{recJ} (bbls)
VEst(bbls)= 77.1BBLs
*Calculation of the respective estimated volume is to be done using the new spill estimation software on site
*Conversion of m3 to barrels is Total volume VT (m3) x 6.29
*Emulsification factor for spill on water to consider is 60% of volume of oil.
25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact After the
initial response and therefore recommend that the site be closed out 🗖
B. Investigation of the incident site showed that there is residual impact on site requiring
further works 🔼
26 Signatorias
26 Signatories
This report was filled and signed on the <u>2_/12011</u> at incident site by joint investigation representatives from
Host Community
• Department of Petroleum Resources [DPR]: □
• National Oil Spill Detection and Response Agency [NOSDRA]:
• State Ministry of Environment [SME]:
Nigeria Police Force [NPF]:□
• Shell Petroleum Development Company [SPDC]:
Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0066 744907

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: ______U066 744907

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
	155884	321954
	155884 155888 155903 155907 15592	321952
	155903	321971
	155907	32-19 68
	15592	321981
	155918	321981
	155919	321992
li .		