JOINT INVESTIGATION REPORT FOR INCIDENT NO."	0043	711029
JOINT INVESTIGATION REPORT FOR INCIDENT NO.		

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:		
. Spill incident Number: 7110	2.Type c	of incident* OIL SPILL
. Name of Location BATAN	WELL HT (	6 INCH FLOW LINE
. Name of nearest community [SAT	<b>~ м</b> 5. State: <b>D</b>	ELTA 6. LGA WARRI - SOUTH
7. Type of Production facility/Installation	FLOWLING 8. A	Asset owner/District NWSI
B. INCIDENT INFORMATION:		
b. Date/Period of investigation:	2/09/2011	1600 HRS @ 1330HRS
c. Description of spill point enviror		<del></del>
Firmed soil	□ Loose soil	☐ Previously excavated area
☐ Under water	□ Swampy	☐ Exposed pipe surface
☐ Well Platform (on Water)  d. Description of leak point (tick as		□ Rig
☐ Drilled hole	☐ Hack saw cut	☐ Explosive tear,
☐ Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap	valve,	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunker	ring) point,	☐ Third party tampering with Clamp
☐ Third party tampering with va	ılve setting,	☐ Third party tampering with flange,
□ External Corrosion		Internal Corrosion
□ Saver-pit over flow,	☐ Surge vessel overflow	v, D Outward dent
☐ Flare System/Bund wall Failu	re 🗆 Valve Failure	com unit failure
□ Cold vent	☐ Relief valve failure	☐ Others (specify)
e. Incident due to:  Third party interference	<b>Operational</b>	☐ Others (specify
f. Spill point coordinates  Measuring unit		
Northing: 1695 7		Easting: 346003 m

Page 1 of 9

<sup>\*</sup>This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

# THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: C. RISK ASSESSMENT 10. Type of environment: Land □ Swamp □ Water ☐ Seasonal swamp Type of environment to which oil has spread: Land □ Swamp ☐ Water ☐ River (identify) \_ ii. Weather condition Sunny □ Raining 11. Distance from the nearest sensitive habitat ☐ Government reserved and designated protected area MI Lm] ☐ Drinking water source ☐ Built up area ☐ Farmlands ☐ Fish Farm/Pond ☐ Fishing net □ Others (specify). 12. Containment measures put in place; Trench □ Booms □ Dyke ☐ Others: 13. Any pictures or video coverage? 14. Was there any disruption to the investigation? If yes give brief description: APPLICA BL

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
A	CONG U	UTH 1	4 A	zed of	/mpac/
<u> </u>	<u> </u>				

JOINT INVESTIGATION REPORT FOR INCIDENT NO: ... 0043 7 110 29

#### 16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	11000			READ	<b>y</b>	- 10 T
-	1710171		1 100 X	RE70	FIM	PACI


#### 17. Fish/Nets/Ponds

S/N	Fish/Net	ts/Ponds	Descrip	otion	Quantity/Size	Comments
N	ONE	Wit	Hear	AREA	OF. U	RPACT

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size	Comments
Monre	WITHIMP	PEA OF	IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0043 711029

# F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
	169571	346004
,	na	•
	1.00	

#### G. INCIDENT INFORMATION:

20	<b>Impacted</b>	A	Data	1.
ZU.	Impacted	Alta	Detai	us

	Total calculated area of impact	_
	• Impact within SPDC R.O.W	_
	Impact outside R.O.W	
21.	Volume of oil recovered before completion of JIV (V <sub>rec</sub> J):	
	Recovered oil V <sub>rec.J</sub> .	barrels
20.	Computation of the residual volume on site	
a.	Computation of volume of pool of free phase oil (on land or confined water body).  i. Area (m²) occupied by pool of free phase oil	_
	ii. Average Depth (m) of pool of free phase oil	_
	iii. Emulsification factor:	
	iv. Volume of pool of free phase oil. V <sub>pool</sub> :	barrels

JOINT INVES	STIGATION REP	ORT FOR INCIDENT	ŊO:_	0043 711029
b. Computation of	of volume of infiltr	rated oil in the soil (V <sub>inl</sub>	<sub>r</sub> ).	
	i. Area (m²) cove	ered by the oil:		NIL
i	i. Area of the poo	ol of free phase oil in to	ouch w	rith soil: NIL_
ii	i. Average Depth	(m) below ground sur	face of	finfiltration of oil: NIL
iv	v. Soil type: S	AND Y CL	44	
,				7 APPLICABLE
i	v. Volume o	f infiltrated oil. Vinf		N1 L barrels
i. Total area o	of oil on open wate erage depth of oil o	on open water based er: NIL on water based on colora		·—
	Thickness (mm)	Percentage coverage		Volume (m3)
Barely Visible	0.00004			, 6
Silvery	0.00008			CARCO
Slight Color	0.00015			CN
Bright Color	0.0003		261	<u></u>
Dull	0.001	_ &\		
Dark	0.002	-67/		
Black oil	0.1	00		
Emulsion (30% Oil)	1			
	Percent Total	1	00%	Total Volume NIL bbl
Γ	iii. Volume of oi	I on open water. Vwat:		NIL barrels
22. Calculation of	of evaporated vol	ume:	•	
		4 MEDIU	rv.	
ii. E-Fa	ctor: 15	<u> 1</u> a		
ii	i. Volume of ev	aporated oil. V evap:		O.18 barrels

Evapor	ration Factors (E-Fa	actor) for SPDC Crue	de oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

23. Gross Total Estimated Spilled Volume  $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$ 

JOINT INVESTIGATION REPORT FOR INCIDENT NO:
V <sub>Est</sub> (bbls)= 1.22 BBLs
24. Net Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + $
$V_{pool}$ (bbls) + $V_{recJ}$ (bbls)
VEst(bbls)= 1-22 BBLs
*Calculation of the respective estimated volume is to be done using the new spill estimation software on site *Conversion of m3 to barrels is Total volume VT (m3) x 6.29
*Emulsification factor for spill on water to consider is 60% of volume of oil.
25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact. After the
initial response and therefore recommend that the site be closed out
B. Investigation of the incident site showed that there is residual impact on site requiring
further works
26 Signatories  This report was filled and signed on the 12/09/20 11 at incident site by joint
investigation representatives from
Host Community
• Department of Petroleum Resources [DPR]: □
• National Oil Spill Detection and Response Agency [NOSDRA]:
State Ministry of Environment [SME]:
Nigeria Police Force [NPF]:
• Shell Petroleum Development Company [SPDC]: ☐

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0043 711029

20. Appendix 1: Overview sketch of the site

Location: BATEN WELL 4T 6" FLOWLING	
	ļ
WELC 47	0.0
WELL 4!	
Q	
Q P	
SPILL 6 INCH FLOWLIA POINT 6 CLOCK	16
@ 6° CLock	
WATR	,
FIELD LOGISTIC	
BASE	

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

#### 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
<u></u> .		
<del></del>		
	<del>                                     </del>	
	+/	
	<del>/</del>	