JOINT INVESTIGATION REP	ORT FOR INCIDENT	NO: 0111715039	
(Note: As practicable as possible the JIT r	report is to be signed in		
A. GENERAL INFORMATION:	_	y with puriody mining partiesy	
1. Spill incident Number: 71503	a 255		
3 Name of Location 2011	2.1y	pe of incident* OIL SPILL	
3. Name of Location 20" Kol	OCREEK -	RUMUEKPE PIPELINE	
4. Name of nearest community OGRO	GOLO_5. State:_F	RIVERS 6. LGA AHOADA - WEST	
7. Type of Production facility/Installation	DIL PIPELINE	3. Asset owner/District NESP/KOLOCREE	
B. INCIDENT INFORMATION:		HE ST NOTOCKEEN	`
) Details action to			
D. Details of incident a. Date of incident: 18TH	SEPTEMBER	. 2011	
b. Date/Period of investigation: 23	RD AND 24TH	H SEPTEMBER 2011	
c. Description of spill point environm		a controlly, will	
Firmed soil	Loose soil	Previously excavated area	
☐ Under water	□ Swampy	☐ Exposed pipe surface	
□ Well Platform (on Water)		□ Rig	
d. Description of leak point (tick as a	pplicable);	— 6	
☐ Drilled hole	☐ Hack saw cut	☐ Explosive tear,	
☐ Complete Rupture	☐ Inward dent,	☐ Well head tampering	
☐ Failed Weld-on illegal hot tap v	alve,	☐ Missing Pipeline/Flowline)	
Crude oil theft (illegal bunkerin	g) point,	☐ Third party tampering with Clamp	
☐ Third party tampering with valv	e setting,	☐ Third party tampering with flange,	
☐ External Corrosion		☐ Internal Corrosion	
☐ Saver-pit over flow,	☐ Surge vessel overflo		
☐ Flare System/Bund wall Failure	☐ Valve Failure	□ com unit failure	
□ Cold vent	☐ Relief valve failure	Others (specify) FAILED CLAMP	
e. Incident due to:		4 omes (speed) THILED CLAMP	
☐ Third party interference	-/ a	_	
Limit party interference	Operational	☐ Others (specify NOT APPLICABLE	,
f. Spill point coordinates (MINN	A MID - BELT)		
Measuring unit M	i in beety		
Northing:		Easting:	
104913-43		454954-11	
		てってつって・リ	
			•
		İ	
•		ı	

Page 1 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0111 715039

G.	KISK ASSESSME	NI			
	10. Type	of environment:		>	
	Land	□ Swamp	□ Water	☐ Seasonal swamp	
	i. Type o	f environment to	which oil has sp	pread:	
	Land	□ Swamp	☐ Water	□ River (identify) No⊤	APPLICABLE
	ii. Weath	er condition			
	☐ Raining 11. Distance from t	. Sunny he nearest sensit	ive habitat		
	☐ Drinking w☐ Built up ard☐ Farmlands☐ Fish Farm/☐ Fishing net	Pond cify). NoT	APPLICA	[,m] [,m] [,m] [,m] ,m]	
	Booms	Trench	✓ Dyke		
	✓ Others:	NATURA	L DEPR	ESSION	
	13. Any pictures or	video coverage?	,	[Y] / [N]	
	14. Was there any o	lisruption to the	investigation?	[Y] [N /	
If y	ves give brief descript	ion:	API	PLICABLE	-

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number		Comments
A	ONE	WITH	IN P	REA	OF	IMPACT

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0111715039

16. Crops/Economic Trees


S/N Type of crops	Young	Medium	Matured	Quantity	Comments
NONE	WITHIN	ARE	A C	=	ACT

17. Fish/Nets/Ponds

S/N	Fish/Nets/	Ponds	Description	n.	Quantity/S	ize	Comments
No	NE	TIW	HIN 1	AREA	OF	IN	PACT

18. Others (Specify) i.e. Animal Traps

S/N	Others	-	Description		uantity/Size	Comments
No	NE	W	HIN	AREA	OF	MPACT



JOINT INVESTIGATION REPORT FOR INCIDENT NO: U117 715039

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2) (MINNA MID-BELT)

S/N	Northing (M)	Easting (M)
421	104913.45	454947.95
422	104916.49	454957-20
416	104910-34	454960-26
417	104910-33	454963.35
418	104913.39	454966-44
423	104910.32	454966-43
398	104910.29	454975.67
399	104910-28	454978.75
400	104913.36	454975.68
401	104916-43	454978.77
402	104916-40	454988.02
403	104913.32	454991.09
404	104910.26	454987.99

G. INCIDENT INFORMATION:

20. Impacted Area Details

Total calculated area of impact	06 Ha
Impact within SPDC R.O.W	06 Ha
Impact outside R.O.W	اللـ
21. Volume of oil recovered before completion of JIV (V _{rec}):	
Recovered oil V _{rec} r.	NIL barrels
20. Computation of the residual volume on site	
 a. Computation of volume of pool of free phase oil (on land or confi. i. Area (m²) occupied by pool of free phase oil 	ined water body).
ii. Average Depth (m) of pool of free phase oil	<u>0.008</u>
iii. Emulsification factor:	
iv. Volume of pool of free phase oil. V _{pool} :	23-6 barrels

	i nickness (mm)	coverage	Volume (m3)	_
Barely Visible	0.00004		* =		
Silvery	0.00008		T		
Slight Color	0.00015		<u> </u>		
Bright Color	0.0003				
Dull	0.001				
Dark	0.002	APP	L(AKI F		_
Black oil	0.1	/ \ \ 1 			_
Emulsion (30% Oil)	1				
	Percent Total	100%	Total Volume	-NIL	bbl
Γ	iii. Volume of oi	I on open water. Vwat:	NIL		barrels
22 Calculation o	of evaporated vol	ime.			

22. Calculation of evaporated volume:

i. Oil type: BONNY LIGHT

ii. E-Factor: 25 1/2

iii. Volume of evaporated oil. V evap:	q	barrels

Evapor	ration Factors (E-Fa	actor) for SPDC Crue	de oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) = 9 + NiL + 3.4 + 23.6 + NIL = 36$

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 011175039

VEst(bbls)= 36 BARRELS
24. Net Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) = 9 + NIL + 3.4 + 23.6 + NIL = 36$
VEst(bbls)= 36 BARRELS
*Calculation of the respective estimated volume is to be done using the new spill estimation software on site *Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out.
B. Investigation of the incident site showed that there is residual impact on site requiring further works THOUGH CONTAINMENT WAS IN PLACE, THE NOSDRA REPRESENTATIVE RECOMMENDED THAT RECOVERY OF THE FREE PHASE OIL SHOULD BE DONE AS QUICKLY AS POSSIBLE TO
26 Signatories INTO THE NEARBY ORASHI RIVER.
This report was filled and signed on the 24/09/2011 at incident site by joint investigation representatives from
Host Community
• Department of Petroleum Resources [DPR]: □✓
National Oil Spill Detection and Response Agency [NOSDRA]: □
State Ministry of Environment [SME]:
Nigeria Police Force [NPF]:


• Shell Petroleum Development Company [SPDC]:

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO:_

0111 715039

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 715039 0111

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION (MINNA MID-BELT)

S/N	Northing (M)	Easting (M)
406	104907-16	454997.24
407	104904.08	454997.23
408	104910.19	455.009-57
409	104907.12	455009-56
412	104901-01	454997.22
413	104897.97	454984.88
414	104901.08	454972.56
415	104904-19	454960-25
420	104907-30	454947.93