JOINT INVESTIGATION REPO	RT FOR INCIDENT NO	0; <u>0437</u>
Note: As practicable as possible the JIT re	port is to be signed in the	e field by all the participating parties)
A. GENERAL INFORMATION:		
l. Spill incident Number: 8292	-94 2.Type	of incident * DIL SPILL
-	H-EBUBU K	ELL 5/9 FLOWLINE
		190c SI 5mc
4. Name of nearest community ETEA		
7. Type of Production facility/Installation	TLOWILINE 8. A	Asset owner/ District LAND 1
B. INCIDENT INFORMATION:		
Details of incident a. Date of incident: b. Start date/time of investigation: c. Investigation End date:	2012 19106 2012; 12	L:BS
 d. Description of spill point environm Firmed soil 	ent Loose soil	☐ Previously excavated area
Under water	Swampy	Exposed pipe surface
Well Plateform (on Water)	••	□ _{Rig}
e. Description of leak point (tick as a	_	
□Drilled hole	∐Hack saw cut	Explosive tear,
☐Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐Failed Weld-on illegal hot tap v		☐ Missing Pipeline/Flowline)
☐Crude oil theft (illegal) bunkeri		☐ Third party tampering with Clamp
Third party tampering with val		☐ Third party tampering with flange,
□ Corrosion	☐ Saver-pit over flow,	☐ Surge vessel overflow
☐Outward dent	☐Flare System/Bund v	—
□Valve Failure	Com unit failure	Cold vent
Relief valve failure	Others (specify)	
f. Incident caused by:	_/	_
☐ Third party interference	☑ Operational	□Mystery
g. Spill point coordinates Measuring unit (1)	inna mis -belt	
Northing:		Easting:
86130.55		COHORN
60130.55	,	521127.14
·		

Page 1 of 9

	JOINT INVEST	IGATION REP	ORT FOR INC			237	_	
c.	RISK ASSESSMEN	NT		82	192	94		
	10. Type o	of environment:		- •		• •		
	Land	□ Swamp	□ Water	□ Sea	sonal swa	ımp		
	i. Type of	f environment to	which oil has sp	read:				
	Land	□ Swamp	□ Water	□ Rive	er (identit	fy)		
		r condition						
	Raining 11. Distance from the	□Sunny ne nearest sensiti	ve habitat				•	
	Governmen Drinking was Built up are Farmlands Fish Farm/F Fishing net Others (spe	a Pond cify).		ed area	[[[[[,m] ,m] ,m] ,m] ,m]		
	□ Booms	☐ Trench	□ Dyke					
	Others:	No	NE		_			
	13. Any pictures or	video coverage?				[N]		
	14. Was there any d	isruption to the i	nvestigation?		[Y]	[\\		
If y	es give brief descripti	on:						
_		N	ONC					
D.	TYPE/NUMBERS (OF PROPERTI	ES, IF ANY, FO	UND WIT	HIN THE	E AREA OF	SPREA	D OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
	~11.			1-1	
<u> </u>	NI A	N <i>IA</i>	N-A	<u> </u>	\ \/- <u>\</u>
		ļ <u>'</u>	1.1//	'\/	' \
		1			

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0237

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	ļ					
	NA	NL	NA	TN/A	NA	NA
	<u> </u>	14/	1,44,,	 11/11 	1 11,	


17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	7///	1/4	N/A	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
ſ ⁻	/ \ // \	N/ A	/ ¥ [/ \	/ \\

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	AA	NIA -	X/X	A / A
	/4/\	1476	1975	/ \\ \

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)



JOINT INVESTIGATION REPORT FOR INCIDENT NO:____

/N	Northing	Easting /
	 	
	 - · / -	
	/	
		7
	/	
	 	
	 	
		/
	!	
INC	CIDENT INFÓRMATION:	<u>.</u>
	. Impacted Area Details	
20	-	LESS THAN 3M2
	Total calculated area of impact	YES
	Impact within SPDC R.O.W	185
21	Impact outside R.O.W Volume of oil recovered before completion	of IIV (V
21.	Recovered	Company of the control of the contro
		oil Vict barrel

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 0237 JOINT INVESTIGATION REPORT FOR INCIDENT NO: iii. Emulsification factor: iv. Volume of pool of free phase oil. V pool: . barrels Computation of volume of infiltrated oil in the soil (Vinf). i Area *(m2) covered by the oil:___ ii Area of the pool of free phase oil in touch with soil: 0.02n iii Average Depth (m) below ground surface of infiltration of oil: Soil type: ίv P_c (effective porosity of the soil). Volume of infiltrated oil, Vint 21. Computation of volume of oil on open water based on standard coloration. Total area of oil on open water: i. Table of average depth of oil on water based on coloration ** Thickness Percentage (mm) coverage Volume (m3) Barely Visible 0.00004 Silvery 0.00008 Slight Color 0.00015 **Bright Color** 0.0003 Dull 0.001 Dark 0.002 Blackoil 0.1 Emulsion (30% Oil) Percent Total 100% Total Volume bbl iii. Volume of oil on open water. Vwat 🐇 barrels 22. Calculation of evaporated volume: Oil type: BONNY MEDIUM i. ii. E-Factor: iii. Volume of evaporated oil. V coaps D. 000 I

Evaporation Factors (E-Factor) for SPDC Crude oil				
Oil Type	Days on site	Bonny Light	Bonny Medium	
Period Since Öil Spill	< 1 day	10%	5%	
	1-7 days	25%	15%	
	> 7 days	40%	25%	

** Spill Factor from USCG FOG (2000 Edition)

^{*}If area is not same as the total area of impact, please indicate in the overview sketch


JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0237

23. <u>Gross Total Estimated Spilled Volume</u>
$V_{tst}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls)$
$V_{\text{Est}}(\text{bbls}) = 0.007$
24. Net Total Estimated Spilled Volume
$V_{Est}(bbls) = V_{evap}(bbls) + 0.6*V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls)$
VEst(bbls)= 0.0007
*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site
*Conversion of m3 to barrels is Total volume VT (m3) x 6.29
*Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE
25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact after the
initial response and therefore recommend that the site be closed out 🗹
B. Investigation of the incident site showed that there is residual impact on site requiring
further works
26 REPRESENTATIVES
This report was filled and signed on the investigation representatives from
Host Community ✓
• Department of Petroleum Resources [DPR]: □
• National Oil Spill Detection and Response Agency [NOSDRA]:
State Ministry of Environment [SME]: ✓
Nigeria Police Force [NPF]:□ ,
Shell Petroleum Development Company [SPDC]: ✓
Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

27. Appendix 1: Overview sketch of the site

829294



JOINT INVESTIGATION REPORT FOR INCIDENT NO:

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
	,	
	<u> </u>	
i		/ .
	, ,	
· -		