## JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0275 82865 9

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

A. GENERAL INFORMATION:	_	
and the second s	ബ	•
I. Spill incident Number: 839 62	2.Type	of incident * OIL SPILL
3. Name of Location DB19BO NCC	TH'WELL 28 1/5	FLOWLINE
4. Name of nearest community IMEH	5. State: <u>R\V</u>	ER 6. LGA ETCHE
7. Type of Production facility/Installation 🖸	ILFLOWLINE 8. A	Asset owner/ District NEL1/PHC1
B. INCIDENT INFORMATION:		
9. Details of incident  a. Date of incident: 13 THILLIE  b. Start date/time of investigation: 15  c. Investigation End date: 15 THILLIE  d. Description of spill point environment	WE 2012.	
☐Firmed soil	Loose soil	Previously excavated area
☐Under water	□Swampy	☐Exposed pipe surface
☐ Well Plateform (on Water)		□Rig
e. Description of leak point (tick as a	pplicable);	<b>G</b>
Drilled hole	☐Hack saw cut	☐Explosive tear,
Complete Rupture	☐ Inward dent,	☐ Well head tampering
Failed Weld-on illegal hot tap v	alve,	Missing Pipeline/Flowline)
Crude oil theft (illegal) bunkers	ing) point,	☐ Third party tampering with Clamp
☐Third party tampering with val	ve setting,	☐ Third party tampering with flange,
□Corrosion	☐Saver-pit over flow,	☐ Surge vessel overflow
Outward dent	☐Flare System/Bund v	<del>-</del>
□Valve Failure	Com unit failure	☐ Cold vent
☐Relief valve failure	Others (specify)	
f. Incident caused by:		
Third party interference	☐ Operational	□ <sub>Mystery</sub>
g. Spill point coordinates  Measuring unit	WONDA-M	D BELI
Northing: (m)		Easting: (m)
101832.60		512793.53
	1	
No.		•
· ·		

Page 1 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO:	0275	82865 <b>9</b>

Ç.	RISK ASSES	SMENT		-	
	10.	Type of environment:			
	<b>☑</b> Land	□ Swamp	□ Water	☐ Scasonal swamp	
	i. T	ype of environment to	which oil has sp	spread:	
	<b>√</b> Land	□ Swamp	□ Water	□ River (identify)	
	ii. V	Veather condition			
	☐ Rainir 11. Distance fi	ng Sunny rom the nearest sensiti	ve habitat		
	☐ Drink ☐ Built t ☐ Farml ☐ Fish F ☐ Fishin ☐ Others	ands arm/Pond		NIL ,m     NIL ,m   NIL ,m     NIL ,m     NIL ,m     NIL ,m     NIL ,m     NIL ,m   NIL ,m     NIL ,m     NIL ,m     NIL ,m     NIL ,m     NIL ,m   NIL ,m     NIL ,m   NIL ,m     NIL ,m   NIL ,	
	□ Boom	s 🗖 Trench	□ Dyke		
	□ Others	NOT APPLI	CABLE		
	13. Any pictur	es or video coverage?		[X] [N]	
	14. Was there	any disruption to the is	nvestigation?	[Y] [X]	
If y	es give brief des	scription:			
	YC	7	API	PLICABLE -	-

#### D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

#### 15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
<del>-</del>		<del> </del> -		<del>-</del>	
	MONE	1 1 1-7	11.1	ADCA	DS IMPACT
	10100	MII	HIV	AKEA	07 11111191
		<del> </del>			
	•				

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

0275 828659

#### 16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	NDA'	WITH	IN A	REA (	7 1	PACT

#### 17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	1 10 h 10	1 17711	1 1 1 1 X 6	11/10/0
-	HUNL	MI HIV	AKLA	14 114 11 AC)
	,			<u> </u>

#### 18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
				* ( ) ( )
	NIDNIC 1	ALTHIN AT	P ( A 1) 5	11/12/A(S)
	140/4 <u>L</u>	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		11.11.604
ĺ	<u> </u>			

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1) 12 Eclock Position BRILL HOLE " CRIGGO NORTH REMOVED CHARVESTED PIPE) OBIGBO NORTH WELL SECTIONS SHOWING BRIGBO NORT WELL 28 L FLOWLINE

DRILL HOLE GUT AND HARVESTED

# 

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

MIN NA - MIO DELL

	MIN NA -	
S/N	Northing (m)	Easting (m)
188	512190.101836.55	512790.36
-186	101835.24	512793.33
187	101881-51	512798 98
188	101827.70	512794.88
183	101832.61	512787 · 37
	<u>_</u>	

#### G INCIDENT INFORMATION:

Total calculated area of impact Impact within SPDC R.O.W  Total calculated area of impact  Total calculated area of impact  Total calculated area of impact  Total calculated area of impact	
Impact outside R.O.W	
21. Volume of oil recovered before completion of JIV (V <sub>rec</sub> J):	
Recovered oil V	barrels
20. Computation of the residual volume on site	
a. Computation of volume of pool of free phase oil (on land or confined water body).	•
ii. Average Depth (m) of pool of free phase oil	

THE SHELL PE	TROLEUM D	EVELOPMENT COM	IPANY OF	· NIGERIA	LIMITED	
JOINT INVE	STIGATION REF	PORT FOR INCIDENT	NO:	0275	82865	9
	k / 1 #					
iii. Emulsification	factor:	<u> </u>				
iv.	Volume of	pool of free phase oil. $V_{po}$	ol:	0315	BARKEL	barrels
b. Computation	of volume of infile	trated oil in the soil ( $V_{inf}$ )				
i		overed by the oil:	50 m	2		
i	i Area of the po	ool of free phase oil in tor	ch with soi	i: NIL	_	
i		th (m) below ground surfa				M
i	v Soil type:		oc or mind	ation of on.	<u> </u>	
- -		porosity of the soil).	8%			
		- Confidence of N	0.07			
	v. volume (	of infiltrated oil. V <sub>inf</sub>	0.07	<u>5</u>	<u> </u>	barreis
21. Computation	of volume of oil	on open water based o	n standard	coloration		•
	of oil on open wate				•	
ii. Table of ave	rage depth of oil o	n water based on coloration	**			
	Thickness	Percentage				
,	(mm)	coverage		olume (m	3)	
Barely Visible	0.00004			_		
Silvery	0.00008					
Slight Color		1 - 7	401	<del></del>		
Bright Color Dull	0.0003 0.001	<del>                                     </del>	HVL	HAT-	<del>5/ }`</del> -	
Dark	0.002		<del>, , ,</del> ,		<u></u>	
Blackoil	0.1					
Emulsion (30% Oil)		·				
(/	Percent Total	100	)% To1	tal Volume	bb1	]
· iii.	Volume of o	il on open water, Vwar	NIL			barrels
22. Calculation o		i ideal communication of the said	INIL			
i. Oil t	ype: BONNY	MEDIUM				
ii. E-Fa	ctor: 15%	<u> </u>				
iii.	Volume of ev	vaporated oil V	0	.06		barrels
T	dan Erata - /E E	And for SDDC C. 1. 11		1		<u></u>
Oil Type	Days on site	tor) for SPDC Crude oil  Bonny Light Bor	NTS7	-		
~~ ~JP~	Days on six	2000 Marie Doi	1. 11.			

Evaporation Factors (E-Factor) for SPDC Crude oil							
Oil Type Days on site Bonny Light Bonny							
			Medium				
Period Since Oil	< 1 day	10%	5%				
Spill							
	1-7 days	25%	15%				
	> 7 days	40%	25%				

<sup>\*</sup>If area is not same as the total area of impact, please indicate in the overview sketch

\*\* Spill Factor from USCG FOG (2000 Edition)

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0275 828659

23. Gross Total Estimated Spilled Volume		
$V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recl}(bbls)$		
YEST (bbls)= 0.06+ 0.025+0.315+NIL= 0.4 BARREL		
24. Net Total Estimated Spilled Volume		
$V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + 0.6*V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recJ}}(bbls)$		
VESt(bbls)= 0'06+ 0.025+0:315 + NIL = 0'HBARREL		

#### 25. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

#### 26 REPRESENTATIVES

This report was filled and signed on the  $\underline{15}/\underline{66}/20\underline{/2}$  at incident site by joint investigation representatives from

- Department of Petroleum Resources [DPR]: 💢
- National Oil Spill Detection and Response Agency [NOSDRA]: ☑
- State Ministry of Environment [SME]: ✓
- Nigeria Police Force [NPF]:💢
- Shell Petroleum Development Company [SPDC]: ☑

Tick as applicable


<sup>\*</sup>Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site

<sup>\*</sup>Conversion of m3 to barrels is Total volume VT (m3) x 6.29

<sup>\*</sup>Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0275 828659

#### 27. Appendix 1: Overview sketch of the site



## THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 10275828659

### 21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
185	101836.55	512790.36
186	101835.24	512793.33
187	101831.51	512792.98
188	101827.70	512794.88/
189	101832.61	512787.37
,		
<b></b>		