THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0309					
(Note: As practicable as possible the JIT i	report is to be signed in th	e field by all the participating parties)			
A. GENERAL INFORMATION:					
1. Spill incident Number: 83153	372.Type	of incident * OIL SPILL			
3. Name of Location OPUKUSHI	WELL 247	T FLOWLING			
AGBEN 4. Name of nearest community ANGA	10 — LEBIRI 5. State: BA	FLOWLING YELSA 6. LGA EXEREMO			
7. Type of Production facility/Installation	FI-OWLINE 8.	Asset owner/ District WWS 2			
B. INCIDENT INFORMATION:					
9. Details of incident a. Date of incident: 23 6 20 b. Start date/time of investigation: 2 c. Investigation End date: 30 6 7 d. Description of spill point environt	51612012@1620	34-0 HRS OHRS			
☐Firmed soil	Loose soil	Previously excavated area			
Under water	Nampy Swampy	☐ Exposed pipe surface			
	applicable);	$\square_{ m Rig}$			
□Drilled hole	□Hack saw cut	☐Explosive tear,			
☐Complete Rupture	☐ Inward dent,	☐ Well head tampering			
Failed Weld-on illegal hot tap	valve,	☐ Missing Pipeline/Flowline)			
Crude oil theft (illegal) bunke	ring) point,	☐ Third party tampering with Clamp			
Third party tampering with va	lve setting,	☐ Third party tampering with flange,			
Corrosion	☐ Saver-pit over flow,	☐ Surge vessel overflow			
Outward dent	Flare System/Bund	wall failure			
□Valve Failure	Com unit failure	Cold vent			
Relief valve failure	Others (specify)				
f. Incident caused by: [*] □Third party interference	Doperational	□Mystery			
g. Spill point coordinates Measuring unit					
Northing:		Easting:			
10100	75m	371581m			
		· ·			

Page 1 of 9

^{. *}This can be a) Oil spill b) Drilling fluid/Chemical c) siltation d) construction e) Encroachment f) Fire,

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0309 831537 JOINT INVESTIGATION REPORT FOR INCIDENT NO:__

C. F	RISK ASSE	SSMENT				,			
	10.	Type of enviro	nment:		•	.			
	□ Lan	d 🖾 Sw	amp 💆	Vater □	Scasonal swamp	* **			
	i.	Type of environ	nment to which o	oil has spread:					
	□ Lan	d 🖫 Swa	amp 🖂 🤻	Vater □	River (identify)				
	ii.	Weather conditi	ion						
	⊠ Rair 11. Distance	ning Sur e from the neares		at					
	□ Dri □ Bui □ Far □ Fisl □ Fisl □ Oth	vernment reserve nking water sour ilt up area mlands h Farm/Pond hing net ners (specify). ument measures p	rce	d protected area	[N/L,m] [O ,m] [S,m] [N/Lm] [N/Lm]				
	D Boo	oms 🗆 Tre	ench 🗆 🗆) yke					
	□ Oth	iers:	, -						
	13. Any pic	ctures or video co	overage?		[N]				
	14. Was the	ere any disruption	n to the investiga	ation?	[Y] [N]				
lf ye	f yes give brief description:								
	NOT APPLICABLE								
		IBERS OF PRO		ANY, FOUND	WITHIN THE AREA OF	SPREAD OF OIL			
S/N	Type of	Structures	Description	Size	Number	Comments			
	VOA	JE M	VITH	NAI	CEA OF	IMPACT			

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0309 831537

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	MANGROVE	· /	425		LOT.	
			/			
7			,			7

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
			ļ	
	UNG WITH	ME AREA O	FIMPA	CT

18. Others (Specify) i.e. Animal Traps

S/N	Others		Description		Quantity/Size		Com	ments	
							1		
$\perp \Delta L$	ME	WIT	HIN	HREI	4_1	2F_	IMPA		
1 0			,,,, <u>,</u>	711-0.		·	· ·		
	İ	l							

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

OPUKUSHI WELL 24 T FLOWLING (6"

INTERNAL CORRUSION

@ 6,0° CLOCK POSITION

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0303831537

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

S/N	Northing	Easting
SP pt	101005	371581
1	101007	371 577
2	100998	371 566
3	100 977	371 544
4	100999	37/ 592
5	101003	37/ 609
6	101019	37/ 588
7	101038	371 506
8	101060	371355
9	101 115	37/130
10	101289	370 922
11	10/337 337	370901
12	101090	371 559

G. INCIDENT INFORMATION:

21.	Total calculated area of impact Impact within SPDC R.O.W Impact outside R.O.W Volume of oil recovered before completion of JIV (V _{rec.J}): Recovered oil V _{rec.J} :	barrels
20. a.	Computation of the residual volume on site Computation of volume of pool of free phase oil (on land or confined water body). i. Area (m²) occupied by pool of free phase oil NOT APPLIC	ABLE

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED							
JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0309 831537							
iii. Emulsification factor: NOT APPLICABLE							
iv.							
b. Computation of	of volume of infilt	rated oil in the soil (V).				
b. Computation of volume of infiltrated oil in the soil (V _{inf}). i Area *(m²) covered by the oil: 150 m²-							
íi	Area of the po	ool of free phase oil	in touch	with soil:	11		
ii	i Average Dept	h (m) below ground	surface o	of infiltration of oil:	0.15M		
i				.•			
¥	P_e (effective	porosity of the soil).	. 8	50/0			
iv	v. Volume o	of infiltrated oil. V	inf		11.32 barrels		
•							
21. Computation			sed on s	tandard coloration	l.		
Total area o Table of aver	f oil on open water	عد رستر ا In water based on colo	ration				
ii. Table of aver	age acparorone	if water based on color	anon				
	Thickness (mm)	Percentage coverage	e	Volume (m	13)		
Barely Visible	0.00004	50%	,	0400143			
Silvery	0.00008	150/	9	0.00085	8312		
Slight Color	0.00015						
Bright Color	0.0003	29	G	0-000429	156		
. Dull	0.001	30/	o	0.002145	78		
Dark	0.002			1 23000			
Black oil	0.1	13%	0	1707259			
Emulsion (30% Oil)		12.	6	10.1289	11.0;		
·	Percent Total		100%	Total Volume	11.81 143		
iii.		il on open water. \	/wat		74.26 barrels		
22. Calculation o	f evaporated vol	lume:					
i. Oil t	ype:BONNY	MEDIUM					
	- 0						
ii. E-Factor: 15 70							
iii.	Volume of e	vaporated oil. V evap:			20.4 barrels		
		tor) for SPDC Crude					
Oil Type	Days on site	Bonny Light	Bonny Mediur	n			
Period Since Oil	< 1 day	10%	59				
Spill		 					
	1-7 days	25%	15	 -			
	> 7 days	40%	25	70			

Page 5 of 9

^{*}If area is not same as the total area of impact, please indicate in the overview sketch ** Spill Factor from USCG FOG (2000 Edition)

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED


JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0303 831537
23. Gross Total Estimated Spilled Volume
$V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recJ}}(bbls)$
Visi(bbls)= 135,97BBLs
24. Net Total Estimated Spilled Volume
$\mathbf{V}_{\text{Est}}(\text{bbls}) = \mathbf{V}_{\text{evap}}(\text{bbls}) + 0.6*\mathbf{V}_{\text{wat}}(\text{bbls}) + \mathbf{V}_{\text{inf}}(\text{bbls}) + \mathbf{V}_{\text{pool}}(\text{bbls}) + \mathbf{V}_{\text{recJ}}(\text{bbls})$
VESt(bbls)= 106 27 BBLS
*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site
*Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil.
25. GENERAL STATUS OF THE SITE
A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out
B. Investigation of the incident site showed that there is residual impact on site requiring further works
26 REPRESENTATIVES
This report was filled and signed on the $25930/06/20/2$ at incident site by join investigation representatives from
Host Community
• Department of Petroleum Resources [DPR]: □
• National Oil Spill Detection and Response Agency [NOSDRA]:
• State Ministry of Environment [SME]: □
• Nigeria Police Force [NPF]:□
Shell Petroleum Development Company [SPDC]: □
Tick as applicable

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIALIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

83153

27. Appendix 1: Overview sketch of the site



THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 13.19831537

JOINT INVESTIGATION REPORT FOR INCIDENT NO:

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
	101 095	37/620
	101014	37/719
	1:00 953	371724
	100 888	37/ 772
	100930	37/ 788
	100699	371954.
	100535.	3721/2.
	100417	372218.
	100-417	3719
	100139	37/ 957
	100472	371 265
	100 755	37/949
	100870	37/957
	100874	37/838