# THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0286 834048

(Note: As practicable as possible the Ji	ι report is το be signed in τη	e neid by all the participating parties)
A. GENERAL INFORMATION:		•
1. Spill incident Number: 834	048 2.Type	of incident * OIL SPILL
3. Name of Location 4" 0	BELE - IBA	A PIPELINE
	•	JERS 6. LGA EMDHUA
7. Type of Production facility/Installation	on OIL PIPELINES.	Asset owner/ District NPE / PH
B. INCIDENT INFORMATION:		
9. Details of incident  a. Date of incident: 28TH  b. Start date/time of investigation  c. Investigation End date: 2N  d. Description of spill point envir	onment 2012.	12.
Firmed soil	Loose soil	✓ Previously excavated area
□Under water	$\square_{\text{Swampy}}$	Exposed pipe surface
☐ Well Plateform (on Water)	Cashla).	$\square_{Rig}$
e. Description of leak point (tick		
Drilled hole	Hack saw cut	☐Explosive tear,
Complete Rupture	∐Inward dent,	☐ Well head tampering
Failed Weld-on illegal hot t	-	☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal) but	<del></del>	☐ Third party tampering with Clamp
☐Third party tampering with		☐ Third party tampering with flange,
L. Corrosion	☐Saver-pit over flow,	_
UOutward dent	☐ Flare System/Bund	_
☐Valve Failure	com unit failure	☐ Cold vent
Relief valve failure	Others (specify)	<del></del>
f. Incident caused by:		
Third party interference	☐ Operational	□ <sub>Mystery</sub>
g. Spill point coordinates  Measuring unit 11 275	RS (MID-BE	J) MINNA
Northing:	`	Easting:
10789	38.16	482631.08
*		• .

<sup>. \*</sup>This can be a) Oil spill b) Drilling fluid/Chemical c) siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0286 834 048

C.	C. RISK ASSESSMENT				
	10. Type	of environment:		•	
	🗾 Land	□ Swamp	□ Water	□ Seasonal swamp	
	i. Type o	of environment to w	which oil has spread	d:	
	Land ·	□ Swamp	☐ Water	□ River (identify)	
	ii. Weath	er condition			
	Raining 11. Distance from		e habitat		
	☐ Drinking w ☐ Built up ar ☐ Farmlands ☐ Fish Farm/ ☐ Fishing ne	Pond t ecify). <b>PALM TR</b> leasures put in place	EE PLANTATIC e;	[ ,m] [ ,m] [ ,m] [ ,m] [ ,m]	
	☐ Booms	Trench	□ Dyke		
	Others:				
	13. Any pictures or			FXV [N]	
	14. Was there any	disruption to the in	vestigation?	[Y] [N]	
If y	es give brief descript	tion:	λ	·	
	140		7PPL	ICABLE	
		l /	111 -		

### D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
<u> </u>		ļ <u> </u>			<u> </u>
1				7	
<del>                                     </del>	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	<del> </del>	Λ -		 
H	<del>  (                                   </del>	THAT	<del>/1</del> 21	-A DF	HMPACT
	O I VETT Y	1 THIN	7 1	- · · · · · · · · · · · · · · · · · · ·	<del>                                      </del>
					<u> </u>

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0236 834 048

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
		\ 41.==	N -			
$\mathbb{H}$	DVIE	WI HIM	HRE	A OF	MPA	cT
1 4	U I VI	# # 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				

#### 17. Fish/Nets/Ponds


S/N	Fish/Nets/F	onds	Description	Quantity/S	ize	Comm	ents
-						<u> </u>	
H	A NIE	<del>\//</del> / <del> </del>	TUNN ARE	A OF	ТM	PAC	
1 1 1 1		<del>- Y- Y-  </del>	<del>                                    </del>				

18. Others (Specify) i.e. Animal Traps

S/N	Others		Description		Quantity/Size	Comments
<del>- 1   1  </del>	NE	<del>- \                                   </del>	<del></del>	An E	A NE	MPACT
<del>                                      </del>	<u> </u>	<del>- \\ \\ \</del>	1111N	TIKE	4 4	<del>1'11 11                               </del>

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

SECTION OF 4" OBELE - IBAA PIPELINE AT IBAA SHOWING POSITION OF HACK SAW CUT.



# THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: \_\_\_\_\_ $0286 \ \ 24048$

## F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2) (MINIA MID-BELT)

S/N	Northing (METRES)	Easting (METRES)
1.	107955.62	482638.64
٦.	109 940.28	482674.35
3.	107937.22	482 671. 27.
4.	107940.29	482671.27
5	107921.89	482 658 90
6.	•	482658.89
7.	107912.69	482 652.71
8.	107891-21	482 640.33
9.	107872.82	482627.96
10.	107872.82	48262488
11.	107 888.16	482631.08
12.	107888.18	482624.92
13	-	482618.77

#### G. INCIDENT INFÓRMATION:

20. I	mpacted	Area	Details
-------	---------	------	---------

	Total calculated area of impact	0·195 Ha	
	Impact within SPDC R.O.W		
	Impact outside R.O.W		
21. <u>Vol</u> 1	ume of oil recovered before complet	tion of JIV (V <sub>rec.J</sub> ):	
	Recoter	ed all View? NIL	barrels
20. <u>Con</u>	aputation of the residual volume on	<u>site</u>	
a. Con	nputation of volume of pool of free phas i. Area (m²) occupied by pool of	e oil (on land or confined water body). free phase oil	
	ii. Average Depth (m) of pool of	A 01F	

#### THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 0286 JOINT INVESTIGATION REPORT FOR INCIDENT NO: iii. Emulsification factor: iv. Volume of pool of free phase oil. V beat . barrels 1.32 Computation of volume of infiltrated oil in the soil (V<sub>inf</sub>). Area \*(m2) covered by the oil:\_\_\_\_ Area of the pool of free phase oil in touch with soil: íì Average Depth (m) below ground surface of infiltration of oil:\_ iii iŕ Soil type: CLAY $P_{\rm c}$ (effective porosity of the soil). Volume of infiltrated oil Vist 21. Computation of volume of oil on open water based on standard coloration. NIL Total area of oil on open water: i. Table of average depth of oil on water based on coloration • • ii. Percentage Thickness coverage Volume (m3) (mm) Barely Visible 0.00004 Silvery 80000.0 0.00015 Slight Color **Bright Color** 0.0003 Dull 0.001 0.002 Dark Black oil 0.1 Emulsion (30% Oil) 1 100% Percent Total Total Volume NIL bbi Volume of oil on open water. V🏎 barrele NIL 22. Calculation of evaporated volume: Oil type: BONNY MEDIUM ii. E-Factor: iii. Volume of evaporated oil Wa

Evaporation Factors (E-Factor) for SPDC Crude oil			
Oil Type	Days on site	Bonny Light	Bonny
		l	Medium
Period Since Oil	< 1 day	10%	5%
Spill		•	
	1-7 days	25%	15%
	> 7 days	40%	25%


<sup>\*</sup>If area is not same as the total area of impact, please indicate in the overview sketch

\*\* Spill Factor from USCG FOG (2000 Edition)

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0286 834048	
23. Gross Total Estimated Spilled Volume = 0.92 + NIL + 3. $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) +$	90+
	6-14
VER (bbls) = 6.1 BARRELS	
24. Net Total Estimated Spilled Volume = 0-92+NIL+	3,90
24. Net Total Estimated Spilled Volume $V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + 0.6*V_{\text{wnt}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recj}}(bbls) + V_{\text$	= 6-14
VEst(bbls)= 6.1 ODDACI C	
*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill vol estimation software on site	ume
*Conversion of m3 to barrels is Total volume VT (m3) x 6.29	
*Emulsification factor for spill on water to consider is 60% of volume of oil.	
25. GENERAL STATUS OF THE SITE	
A. Joint investigation of the incident site found that there is no residual impact after	er the
initial response and therefore recommend that the site be closed out	
B. Investigation of the incident site showed that there is residual impact on site requ	uiring
further works	
26 REPRESENTATIVES	ioint
This report was filled and signed on the <u>02/97/2012</u> at incident site by investigation representatives from	,om:
Host Community	
• Department of Petroleum Resources [DPR]: □	
• National Oil Spill Detection and Response Agency [NOSDRA]:	
State Ministry of Environment [SME]:	
Nigeria Police Force [NPF]:	
Shell Petroleum Development Company [SPDC]:□	
Tick as app	licable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0286 834048

#### 27. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0286 834048

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING

J.	IV FOR AREA CALCULATION MET されら	(MID-BELT) MININA
S/N	Northing METERS	Easting Meters
14.		482594.18
15.	107928-17	482603.45
	107912.75	482628:06
17.	107912.73	482 637. 31
18	107934.19	482652.77
19	107958.72	482674.40
20	107915.75	482655.86