

Overview: Part of spill impact on 8" Umuechem-Nkpoku pipeline right of way at Umuechem. Picture was taken during Joint Investigation of 30th March 2012.



<u>Close up:</u> Illegal fitting on 8" Umuechem-Nkpoku pipeline at Umuechem. Picture was taken during Joint Investigation of 30th March 2012.

1