THE SHELL PETROLEUM DEVI	THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED			
JOINT INVESTIGATION REPORT FOR INCIDENT NO: $\frac{0.703/1028053}{}$				
(Note: As practicable as possible the JIT report	is to be signed in the fie	eld by all the participating parties)		
A. GENERAL INFORMATION:				
1. Spill incident Number: 1028053	2.Type of in	ncident*_DIL SPILL		
3. Name of Location 24" ALAKIR1 -	BONNY PIF	ELINE (DISUSED GPHSL)		
4. Name of nearest community LOMATOR	U 5. State: KIVE	ERS 6. LGA BONNY		
7. Type of Production facility/Installation Pye	<u> </u>	et owner/ District PIPELIME		
B. INCIDENT INFORMATION:				
9. Details of incident a. Date of incident: 22MD AUGUST b. Start date/time of investigation: 297H c. Investigation End date: 297H August d. Description of spill point environment Firmed soil	<u>14460st</u> 2013 (sr. 2013	_		
	_	☐ Previously excavated area ✓ Exposed pipe surface		
□ Well Plateform (on Water)	_	☐Exposed pipe surface ☐Rig		
e. Description of leak point (tick as applica	ble);	⊐Rig		
□Drilled hole □H	ack saw cut	☐Explosive tear,		
Complete Rupture	ward dent,	☐ Well head tampering		
Failed Weld-on illegal hot tap valve,		Missing Pipeline/Flowline)		
Crude oil theft (illegal) bunkering) po	· .	Third party tampering with Clamp		
Third party tampering with valve sett	_	Third party tampering with flange,		
Corrosion \square Si	_	Surge vessel overflow		
Outward dent	are System/Bund wall t	-		
□Valve Failure □co	m unit failure	Cold vent		
□Relief valve failure □O	thers (specify)			
f. Incident caused by:				
	perational [Mystery		
g. Spill point coordinates	1 M	10 0 e . T		
	NIPPA-MU			
Northing:	East	ting:(mv)		
57485.0	0(315818.00		

Page 1 of 9

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED 0703 JOINT INVESTIGATION REPORT FOR INCIDENT NO: C. RISK ASSESSMENT 10. Type of environment: Swamp ₩ater □ Land ☐ Seasonal swamp Type of environment to which oil has spread: □ Land **□** Swamp .**□**/Water ☐ River (identify) ii. Weather condition Sunny □ Raining 11. Distance from the nearest sensitive habitat ☐ Government reserved and designated protected area ☐ Drinking water source ☐ Built up area WITHIA VICINITY ☐ Farmlands ☐ Fish Farm/Pond ☐ Fishing net □ Others (specify). 12. Containment measures put in place; Booms □ Trench □ Dyke ☐ Others: 13. Any pictures or video coverage? 14. Was there any disruption to the investigation? If yes give brief description: D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
_					
-	NUNE INT	H/N A	REA	OF IMPACT	
			, , , , , , , , , , , , , , , , ,	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
					

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0703/1028053

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	41	i /1	4 5 -			-
	NUNE	JITHIN	AREA 1	OF IM	PACT	
	<u>'</u>	<u> </u>				

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	1.7			
	NONE AT	THIN AREA	OF IMP	


18. Others (Specify) i.e. Animal Traps

S/N	Others	Descrip	tion	Quan	tity/Size	Comments	
			- <u> </u>				
	NONE	WITHIN	AREA	OF	IMPA	-	
			<u> </u>	+			

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

A SECTION OF 24" ALAKIRI - BONNY PIPELINE AT ILOMATORU

SHOWING A HOLE AT 12 O'CLOCK POSITION



TO BONNY FROM ALAKIRI

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0.703/1028053

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

	an announcing 71
an the state of th	Coordinates (If more than 12 points, Attach as an appendix 2)
19 Impacted area boundary	Cooldinates (1) more man 12 points
1), mpaced area or	La Not-/ T
	MINNA-MUD BELT

	MUMA-	MUD BELL
S/N	Northing ()	Easting (m)
47(57757 . 00	5(5239·00
472	57768 00	515243.00
413	57784.00	515256 0
474	57803.00	515250.00
475	57836 - 00	515251.00
479	57940.00	515396.00
480	57826.00	515549.00
 - - -		
_		

G. INCIDENT INFORMATION:

20	Impacted	Area	Details

	 Total calculated area of impact Impact within SPDC R.O.W Impact outside R.O.W 	2.77Ha TES YES				
21.	Volume of oil recovered before compl	etion of JIV (VrecJ)	:			
	Resor	rered oil V _{ec} u	NIL		barrels	
20. a.	Computation of the residual volume of Computation of volume of pool of free phase i. Area (m²) occupied by pool	on site SEE uase oil (on land or co of free phase oil	ATTACHED onfined water body).	NOTE F OF SPILL	ēr Cor ED Vol	aputation LUME
	ii. Average Depth (m) of pool	of free phase oil				

		•		Y OF NIGERIA LIMITED	
JOINT INVE	STIGATION RE	PORT FOR INCIDE	ENT NO:_	<u>0703//0</u> 280	53
jii. Emulsification	factor:	L			
iv.	Volume of	fpool of free phase oi	l. V _{pool} :	NIL	barrels
b. Computation	of volume of infil	trated oil in the soil	(V_{inf}) .	-1 E	
i	Area *(m²) c	overed by the oil:		481	
i	i Area of the p	ool of free phase oil	in touch w	in boil:	
i		th (m) below ground	.		
i	v Soil type:		ζ.		
	*- —	porosity of the soil).	10,		
· •		of infiltrated oil. V		···	barrels
	v. voidine	or initiated oil.			растеіş
21. Computation	of volume of oi	l on open water ba	sed on star	ndard coloration.	
i. Total area o	of oil on open wat				
ii. Table of ave	rage depth of oil o	on water based on color	ation **		
	Thickness	Percentage	B		
	<u>(mm)</u>	coverage	<u> </u>	Volume (m3)	
Barely Visible	0.00004	•			
Silvery					
Slight Color Bright Color			CARLE		
Dull	0.0003		(***		
Dark		\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	-		
Blackoil	0.1	1	_		
Emulsion (30% Oil)	1	140,		····	
	Percent Total		100%	Total Volume	bbi
iii.	Volume of o	il on open water. V			barrels
22. Calculation o	of evaporated vol	lume:			
	ype: BONHY				
ı. Oli i	Abe: POWW I	<u> </u>			
ii. E-Fa	ector:	.			
iii.	Volume of e	vaporated oil. V evap:	- 11 <i>a</i>	T A PDI (ADI)	1
		inpointed oz. • evap.	NO.	T APPLICABLE	barrels
Evapora	tion Factors (E-Fac	tor) for SPDC Crude	oil		
Oil Type	Days on site	Bonny Light	Bonny		
5 1 1 2 1 2 2 2			Medium		
Period Since Oil Spill	< 1 day	10%	5%		
թիու	1 7 days	250/	1.50/		

Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

^{*}If area is not same as the total area of impact, please indicate in the overview sketch
** Spill Factor from USCG FOG (2000 Edition)

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 6703//028053

23. Gross Total Estimated Spilled Volume
$\mathbf{V}_{\text{Est}}(\text{bbls}) = \mathbf{V}_{\text{evap}}(\text{bbls}) + \mathbf{V}_{\text{wai}}(\text{bbls}) + \mathbf{V}_{\text{inf}}(\text{bbls}) + \mathbf{V}_{\text{pool}}(\text{bbls}) + \mathbf{V}_{\text{recJ}}(\text{bbls})$
$V_{Est}(bbls)_{=}$
24. Net Total Estimated Spilled Volume
$V_{\text{Est}}(\text{bbls}) = V_{\text{evap}}(\text{bbls}) + 0.6*V_{\text{wat}}(\text{bbls}) + V_{\text{inf}}(\text{bbls}) + V_{\text{pool}}(\text{bbls}) + V_{\text{recJ}}(\text{bbls})$
VEST(bbls) = SEE ATTACHED NOTE FOR VOLUME COMPUTATION
*Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume

25. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out $\ \square$ B. Investigation of the incident site showed that there is residual impact on site requiring further works

26 REPRESENTATIVES

29/08/2013 at incident site by joint This report was filled and signed on the investigation representatives from

- Department of Petroleum Resources [DPR]: □
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]: 1
- Nigeria Police Force [NPF]: ☑
- . Shell Petroleum Development Company [SPDC]:□

Tick as applicable

estimation software on site

^{*}Conversion of m3 to barrels is Total volume VT (m3) x 6.29

^{*}Emulsification factor for spill on water to consider is 60% of volume of oil.

Notes on the JIV to 24" Alakiri – Bonny Pipeline (disused GPHSL) at Ilomatoru		
Date of the JIV:		
29 th August 2013	JIV team mobilized to site and JIV was successfully conducted.	
Cause of spills		

The JIV team observed and agreed that the cause of incident is Operational (Corrosion).

Area of impact:

 During the investigation, residual impact was observed on site in form of oil sheen on water and infiltration on swamp. The total area of impact is 2.77(HA).

Volume spilled:

As at the time of investigation, no free phase oil was observed despite the containment boom in place. Also, it was noted that the line is not in use. However, with the observed impact, it is assumed that due to tidal influence, all the spilled oil must have been dispersed. Due to the nature of the incident and the condition of the site, the preferred volume estimation method is based on the spilled volume equation:


$$Vs = AoTCo\sqrt{\frac{2(p-p_a)}{\rho_{lia}}}f$$

- The pressure differential $\Delta p (p p_a)$ at spill point is assumed to be 100,000 N/ m² = 1bar.
- Bonny light is the crude in the line and the density (ho_{lia}) is 850 kg per m 3
- Time (T) from the reported time of the oil leakage to time of the visit is 604800sec.
- Surface area of the hole (A₀) on the line is taken to be 0.00011m² (as measured)
- Standard discharge coefficient (C_o) is taken as 0.62
- The fraction (f) of oil in the pipe during the incident (residual oil) is taken as 1% (disused pipeline)

Based on the above consideration and assumptions, total volume spilled is estimated to be 40.92 barrels, approximately 41 barrels.

Therefore estimated spilled volume is 41 barrels.

27. Appendix 1: Overview sketch of the site



THE SHELL PETROLEUM DEVELOPMENT COMPANY	OF NIGERIA LIMITED
	6703/1028053
IOINT INVESTIGATION REPORT FOR INCIDENT NO:	1040005

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N_	Northing	Easting
		-
		
	·	
		T /
		4
-		
-		
 		
		-
	<u> </u>	