JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1672851 JIV report S/N: 029	7
(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)	•
A. GENERAL INFORMATION:	
1. Spill incident Number: 1072851 2. Type of incident* OIL SPIL	
3. Name of Location 24" NKPOKU - BOMU TRANS NIGER PIRELINE	
4. Name of nearest community EQBALOR 5. State: RNES 6. LGA ELEME	
7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District PIPELINE	SWt
B. INCIDENT INFORMATION:	•
9. Details of incident a. Date of incident: 17th November, 2013 b. Start date/time of investigation: 17th November, 2013 c. Investigation End date: 19th November, 2013 d. Description of spill point environment Firmed soil Recently excavated area	<u>-</u> 4
Under water	, arty
f. Incident caused by: Third party interference (Sabotage ; crude the fitz; Line the fitz; Accidental 3 rd party damage) Operational Others (including Mystery spills) g. Spill point coordinates Measuring unit M Northing: Easting:	
SP= 86856.95 525113.05	

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

IOINT INVES	STIGATION R	EPORT FOR IN	CIDENT NO:	10728		oort S/N: 0	297
	(ASSESSME						
10). Type	of environment:					
	Land	☐ Swamp	□Water	⊠ Sea	ısonal swamp□5	Shoreline/Wat	erfront
	i. Type	of environment to	which oil has	spread:			
	Land	☐Swamp	□Water	□Riv	er (identify)		
	ii. Weatl	ner condition					
11.	Rain Distance from	☐Sunny the nearest sensiti	☐Dry ive habitat	□Wet	□Windy	□Hot	□cool
	☐ Governme ☐ Drinking v ☐ Built up as ☐ Farmlands ☐ Fish Farm ☐ Fishing ne ☐ Others (sp	rea s /Pond et	esignated prote	ected area	[,m] [,m] [,m] [,m] [,m]	Nome Mith Vicin	SEET H NTY
12.	Containment n	neasures put in pl	ace;			_	
	□Booms □Others:	Trench	Dyke	□Na	tural depression	□ Pit	
13.	Any pictures of	r video coverage	?		[Y] [N]]	
14.	Was there any	disruption to the	investigation?		[Y] [N]	/	
If yes gi	ve brief descrip	otion:					
	N	7	AP	PL	1 CA	BI	_€
D. TYP	PE/NUMBERS	OF PROPERT	IES, IF ANY,	FOUND WI	THIN THE ARI	EA OF SPRE	AD OF OIL
15.	Structures / I	Properties					
S/N 1	Type of Struc	tures Descri	iption Size	Nur	nber	Commen	ts
	MIE	1/1	AHN	A	1 1 1 1 C	# [N	Pret

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1072851 JIV report S/N: 0297

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
7	JOHE	Will	(x)	ARCI	1 4	MPRET

17. Fish/Nets/Ponds

S/N Fish/Nets/Ponds	Description	Quantity/Size	Comments
Note	WITHTH	AREA (7 MPACT

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size Comments
NORLE	WITHER	AREA OF IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SECTIONAL VIEW OF 24" NKPOKY - BOMY TRANS NIGER PIPELINE A

EUBALOR SHOWING: ILLEGAL BUNKERING POINT.

LEAK BUR TO 1" LOCALLY INSTAILED BUNKERING FITTING AT 12" CLOCK POSITION

PIPE DEVICED

THROUGH HOLE

WITH MIPPLE

THE

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1072851 JIV report S/N: 0297

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

19.	Impacted area boundary Coordinates (1) ma	- BEIT)
S/N	Northing (M)	Easting (m)
WP 798	86846-17	525113·07· 525137·09
W799	86853 · 83	525 37 . 09
N 800	86866 · 17 86853 · 83 86844 · 65	525 122:27
WP 801	86856 · 97	525 103.80
1 00		7
 		
		1/
	-	/
<u> </u>	<u> </u>	
	 	
<u> </u>		
 	<u> </u>	10
	 	+ (/s/a'
	 	7 112
		19/11/2013
1		<u> </u>

G. INCIDENT INFORMATION:

20. Impacted Area Details

Total calculated area of impact_	0.04 ha	<u> </u>
Impact within SPDC R.O.W	YES	
Impact outside SPDC R.O.W	No	

21. Volume of oil recovered before completion of JIV (V_{recI}):

			Recovered oil V _{reci} :	ON GO IV	1G-	Barrel
22	Computation	n of estimated resid	ual volume on site		·	
a.	Computatio	n of estimated volume	of pool of free phase oi		fined water body).
			y pool of free phase oil	<u> 2001</u>	η <u>ν</u>	-
	ii.		of pool of free phase oil		2(w	
	iii.	Emulsification factors	<u> 30 %</u>			
	iv.	Estimated Vol	ume of pool of free pha	se oil.	z · &l	bar
			V _{poof} :		8.01	
b.			of infiltrated oil in the stated oil at spill point (V			
	i.	Area* (m²) of soil cov	vered by the oil:	$2m^2$		
	ii.	Average Depth (m) al	oove leaking facility i.e	pipeline/flowlin	ne: 1.2 m.	
	iii.		iv. P _e (effective			
	v.	Cause of spill: THIRL	PARTY vi. Oil typ	e: Bount 1	MEIZUM	
	vii.	Oil Residence time or	i site, day: Two De	143		
	viii.		tration below leaking f		ne/flowline: 0	800
	ix.		filtration around spill po			
		x .	-			
		Estimated Volum	e of infiltrated oil at sp	ill point. V _{inf.4} :	3.17	ba
	2. Estin	nated Volume of infilt	rated oil at second spill	point [if applical	ble] (Vinf b)	
	i.	Area* (m²) of soil cov	vered by the oil:	NIL		
	ii.	Average Depth (m) al	ove leaking facility i.e.	pipeline/flowlin	ne: NL	
	iii.	Soil type: NLL	iv. P_{σ} (effective	porosity of the	soil). NIL.	
	v.	Cause of spill:	vi. Oil typ	e: NiL		
	vii.	Oil Residence time or	site, day: NLL			
	viii.	Average depth of infil	tration below leaking fa	acility i.e. pipelii	ne/flowline: Ni	L _
	ix.	Estimated depth of in	filtration around spill po	oi n t:		
	**	stimuted Volume of u	nfiltrated oil at spill poi	NA ET INT	CADDI ICHRICO	arrels
	3. E	AND THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TRANSPORT OF THE PERSON NAMED IN COLUMN TWO IS NAMED IN CO		San	- H ore in the	
	stim	ted Volume of infiltra	ted oil outside immedia	te spill point(s) 1	egion (Vinf c)	
	i.	Area (m2) of soil cove	ered by the oil:	198 m2	•	
	íi.	Area (m²) of the pool	of free phase oil in touc	h with soil:		
	iii.		elow ground surface of		·8) 00 · Q.	ท
	iv.	Soil type: SIT	<u> </u>		<u></u>	_
	v .	P _e (effective porosity	of the soil).	/ •		
		· · · · · ·	Volume of infiltrated oi	<u> </u>	0.48	1

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1072851 JIV report S/N: 0297

ii. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 Edition)

·	Thickness (mm)	Percentage coverage	Volume (m3)
Barely Visible	0.00004		
Silvery	0.00008	NITALO	00001
Slight Color	0.00015	111011 F	い作え
Bright Color	0.0003	1,-0,1	
Dull	0.001	I WILL THE	X
Dark	0.002		
Black oil	0.1	MICIN	11/
Emulsion (30% Oil)	1	qi Cer	

iii. Percent Total 100%

Estimated Volume of oil on open water. Vwar: NoT APPLICABLE Barrels

24. Calculation of evaporated volume:

- i. Estimated Volume available for evaporation within surface area: 12. 46 Sacrels
- ii. E-Factor: 15 %

iii. Estimated Volume of evaporated oil. V_{evap}: 2.29 Barrels

Evaporation Factors (E-Factor) for SPDC Crude oil									
Oil Type Days on site Bonny Light Bonny Medium									
Oil Residence time	< 1 day	10%	5%						
	1-7 days	25%	15%						
	> 7 days	40%	25%						

25. Net Estimated Spilled Volume
$$V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{pool}(bbls) + V_{recl}(bbls) = 2.28 + NUL + 3.65 + 8.81 + NUL = 14.66 RARR(1)$$

Estimated Reported Volume** V_{reo}(bbls)= 15 Breaks

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than I bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no	residual	impact	after	the	initial
	response and therefore recommend that the site be closed out					

D--- 6 -4

10L	_	ESTIGATION										'	-
	В.	Investigation works	on of the	ivicident	site sh	owed t	hat there	is resid	ual impa	ect on si	te req	uiring :	further
	-				_							 	

27. REPRESENTATIVES

This report was filled, agreed and signed on the 19/11/2015 representatives from	by joint	investigation					
Host Community:							
Department of Petroleum Resources [DPR]:							
National Oil Spill Detection and Response Agency [NOSDRA]:							
State Ministry of Environment [SME]:		i					
Nigeria Police Force [NPF]:							
Shell Petroleum Development Company [SPDC]:							
Signatories agree with reported findings:							
 Separate DPR form has been filled out with same findings□ 							
	Tick	as applicable					

28. Appendix 1: Overview sketch of the site

Location: 24"	NKPSKU - BOM	4 TRAN	NIGRE	PIPELINE	- 	GGBKLOR
				·		

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1072851 JIV report S/N: 0297

