THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMTED. JOINT INVESTIGATION REPORT FOR INCIDENT NO: 107-73-14 report S/N: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 2. Type of incident* OIL SPILL 1. Spill incident Number: { ENWO WELL 4. Name of nearest community ELELENWO 5. State: RVERS 6. LGA OBIO / AKPO 7. Type of Production facility/Installation WELL HEAD 8. Asset owner/District LAND B. INCIDENT INFORMATION: 9. Details of incident a. Date of incident: 21st NOVEMBER 2513 b. Start date/time of investigation: 10Th NEVEMBER 2013: 15:00 Hours AND 12 MEETINGS. c. Investigation End date: 13Th NEVEMBER 2013: 15:00 Hours AND 12 MEETINGS. d. Description of spill point environment Recently excavated area ☐Firmed soil Loose soil □Swampy Exposed pipe surface Under water Well Platform (on Water) LAND ☐Drill Rig e. Description of leak point (tick as applicable); Drilled hole Tear (), ☐Hack saw cut ☐Inward dent. ☐Well head tampering Complete Rupture ☐Failed Weld-on illegal hot tap valve, ☐Failed Clamp ☐Missing Pipeline/Flowline ☐ Third party tampering with Clamp Crude oil theft (illegal bunkering) point, Third party tampering with flange, Third party tampering with valve setting, Corrosion ☐ Saver-pit over flow, ☐Surge vessel overflow, ☐Flare System/Bund wall failure ☐Accidental ☐Bulging Outward party Valve Failure Com unit failure □Cold vent equipment impact □Relief valve failure Others (specify) f. Incident caused by: ☐ Third party interference (Sabotage☐; crude theft☐; Line theft☐; Accidental 3rd party damage☐) **D**Operational Others (including Mystery spills) g. Spill point coordinates Measuring unit (1) Northing:

94 762.12

515212.78

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1077374 JIV report S/N: 0355

C.	RISK ASSE	SSMENT							
	10.	Type of envi	ronment:						
	□ Lan	od □s	wamp []Water	Seasona	l swamp□S	horeline/Wat	erfront	
	i.	Type of envir	onment to whic	h oil has spread	d:				
	Lan	id 🗖s	wamp []Water	□River (id	lentify)			
	ii,	Weather cond	ition						
	□Rain 11. Distance		nny C	ÎDry □v bitat	Vet 🗆	Windy	Hot	Cool	
	□ Dris □ Bui □ Fan □ Fish □ Fish	vernment reservenking water sould the parea mlands in Farm/Pond ming net ers (specify).	ved and designa urceNDME WITHIM	ted protected a S 画色や Vi Ci Niで	rrea [[[[[,m] ,m] ,m] ,m] ,m]			
	12. Contain	ment measures	put in place;						
	□Boo	oms □Tı ers: <u>ND ∓&</u>	rench [Dyke CRWF OIL	□Natural o	lepression	□Pit 71m= 87	SOINT	mves tigatom
	13. Any pict	tures or video c	coverage?		N	g [n]			
	14. Was the	re any disruptio	on to the investi	gation?	[Y] [[]/			
If ye	s give brief d	lescription:			_				
	\wedge	107		At		-10	AR	JE	_
		BERS OF PRO	OPERTIES, IF	ANY, FOUN	D WITHIN	THE AREA	OF SPREA	D OF OIL	
S/N	Type of S	Structures	Description	Size	Number		Comments		
									i.

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1077374 JIV report S/N: 0355

S/N	Type of crops	Young		Medium	Matured	Quantity	Comments
	MON	S	M	THIN	ARE	A OF	IMPACT

17. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	MANE	10/11/14/10	ADSA	NE IMPACT
	40.00	AALHITTA	1 1 T X 1	T July TC

18. Others (Specify) i.e. Animal Traps

S/N Others	Description	Quantity/Size Comments
NON	es MITH	N AREA OF IMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

SEE PICTURE
ATTACHED

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

1077374 - ELELENWO WELL 9LS WELLHEAD AT ELELENWO



Elelenwo Well 9LS Wellhead

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1077374 JIV report S/N: 0355

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

S/N	Northing (M)	Easting (M)
855	94 765.15	515 231 27
856	94 759 01	515 231 26
2857	94 755 99	515 203.52
958	94 762.14	515 200.45
2859	94 768 29	515 200. 46
860	94 781.32	515215.88
2001	94 763 19	515 202.79
		· /
 }		

G. INCIDENT INFORMATION:

20. Impacted Area Details

•	Total calculated area of impact	<u>0.0351</u> Hg.	
•	Impact within SPDC R.O.W	YES	
•	Impact outside SPDC R.O.W	No	


21. Volume of oil recovered before completion of JIV (V_{recJ}):

		REPORT FOR INCIDENT N	red oil V _{rec} :	_JIV report S/N: 	0355 Barrels
		RGCO+CI	t don view.		
22	. Computation	n of estimated residual volum	ne on site		
a.	Computatio	of estimated volume of pool of	free phase oil (on land o	or confined water be	ody).
		Area (m²) occupied by pool of	* U		_
	ii.	Average Depth (m) of pool of	free phase oil		_
	iii.	Emulsification factor	CONDEC		
	iv.	Estimated Volume of po	ool of free phase oil,		barrels
		Vpoor	:	NIL	
b.		n of estimated volume of infiltra nated Volume of infiltrated oil a			
	i.	Area* (m2) of soil covered by t	by Oil: 15 T		
	ii.	Average Depth (m) above leak	ng facility e. pipeline/f	lowline:	
	iii.	Soil type: iv.	$P_{\rm e}$ (effective porosity	of the soil)	
	v.	Cause of spill:	vi. Oil type	<u> </u>	
	vii.	Oil Residence time on site, day	FITTO	LT	
	viii.	Average depth of infiltration be	low leaking facility i.e.	pipeline/flowline:_	
	ix.	Estimated depth of infiltration	around spill point:	.	_
		Estimated Volume of infile	rated oil at spill point. V	inta: NA	barrels
	2 Esti	nated Volume of infiltrated oil a			<u>, </u>
	i.	Area* (m²) of soil covered by t			
	ii.	Average Depth (m) above leak			
	iii.	Soil type:	(effective porosity	of the soil)	
	v.	Cause of spill:	vi. Oil type:		
	vii.	Oil Residence time on site, day			
	viii.	Average depth of infiltration be	low leaking facility i.e.	pipeline/flowline:_	
	ix.	Estimated depth of infiltration	around spill point:		
		Estimated Volume of infiltrated	oil at spill point. V _{int b}	Nu	barrels
	3. E	Section of the sectio	7. C. 2.73 assess 1.1.13ses (4.33)	**1	
	stirr	ated Volume of infiltrated oil ou	tside immediate spill po	int(s) region (Vinf o)
	i.	Area (m2) of soil covered by the	ne oil:	66mz	
	ii.	Area (m2) of the pool of free pl		ii: Mu	
	iii.	Average Depth (m) below grou	nd surface of infiltration	of oil:	74 m
	iv.	Soil type: SILT	A		-
	v.	P _e (effective porosity of the so	il). 21 %		
		<u> </u>	f infiltrated oil. At V _{inf}	3.8	barrel

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1074374 JIV report S/N: 0355

II. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 Edition)



24. Calculation of evaporated volume:

- i. Estimated Volume available for evaporation within surface area: 3 X BARLEIS
- ii. E-Factor: 25%

iii. Estimated Volume of evaporated oil. V_{evap}: 1.27 Barrels

Evaporation Factors (E-Factor) for SPDC Crude oil							
Oil Type	Days on site	Bonny Light	Bonny Medium				
Oil Residence time	< 1 day	10%	5%				
	1-7 days	25%	15%				
	> 7 days	40%	25%				

25. Net Estimated Spilled Volume
$$V_{psi}(bbls) = V_{evap}(bbls) + V_{out}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{rec}(bbls) = 1.27 + ML + 3.8 + ML + 1 = 6.07 BALLES

C-07 - FBALLES

Estimated Reported Volume** $V_{ren}(bbls) = V_{ren}(bbls) = V_{re$$$

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of I bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out

B. Investigation of the incident site show works	wed that there is residual impact on site re	equiring further

27. REPRESENTATIVES

Er. REI TWO EXTENSION	
This report was filled, agreed and signed on the 12 / 12 /2013 by join representatives from	t investigation
Host Community:	
Department of Petroleum Resources [DPR]: □	
National Oil Spill Detection and Response Agency [NOSDRA]:	
State Ministry of Environment [SME]:	
Nigeria Police Force [NPF]:	
Shell Petroleum Development Company [SPDC]:	
Signatories agree with reported findings:	
Separate DPR form has been filled out with same findings□	
1	Tick as applicable

28. Appendix 1: Overview sketch of the site

Location :	 	
		•
	-	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1077344 JIV report S/N: 0355

SPOC MELL HEND (NEW 918)

SPILL

SPOC MELL HEND (NEW 918)

THERA OF IMPACT

ON CONCERTS GRAMO

RIGHT OF

INY