

Overview: Part of spill impact on 8" Obigbo North – KomKom Pipeline right of way at Oyigbo. Picture was taken during Joint Investigation of 5th April 2014.



Close-up: Illegal fitting on 8" Obigbo North – KomKom Pipeline at Oyigbo. Picture was taken during Joint Investigation of 5th April 2014.

1