

Overview: Part of spill impact on 4" Obele-Ibaa Pipeline right of way at Omueze/Ibaa. Picture was taken during Joint Investigation of 8th April 2014.



<u>Close-up:</u> Spill due to punctured hole on 4" Obele-Ibaa Pipeline at Omueze/Ibaa. Picture was taken during Joint Investigation of 8th April 2014.

1