

<u>Overview:</u> Part of spill impact on 16" Nun River – Kolocreek Pipeline right of way at Angiama. Picture was taken during Joint Investigation of 13th April 2014.



<u>Close-up:</u> Hacksaw cut on 16" Nun River – Kolocreek Pipeline at Angiama. Picture was taken during Joint Investigation of 13th April 2014.