



Overview: Part of spill impact on 28" Bomu-Bonny Pipeline Right of Way at Oloma. Picture was taken during Joint Investigation of 29<sup>th</sup> November 2014.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Oloma. Picture was taken during Joint Investigation of 29<sup>th</sup> November 2014.