



Overview: Part of spill impact on 10" Diebu Creek Nun River Pipeline Right of Way at Ekowe. Picture was taken during Joint Investigation of 10th December 2014.



Close-up: Hacksaw cut on 10" Diebu Creek Nun River Pipeline at Ekowe. Picture was taken during Joint Investigation of 10th December 2014.