



Overview: Part of spill impact on 20" Opukushi – Brass Creek Pipeline Right of Way at Amabulou. Picture was taken during Joint Investigation of 7<sup>th</sup> December 2014.



Close-up: Illegal fitting on 20" Opukushi – Brass Creek Pipeline at Amabulou. Picture was taken during Joint Investigation of 7<sup>th</sup> December 2014.