



Close-up: Illegal fitting on 30" Nembe Creek Pipeline at Km45 Awoba. Picture was taken during Joint Investigation of 19th December 2014.