



Overview: Part of spill impact on Santa Barbara Well 14S Flowline at Nembe - Bassambiri. Picture was taken during Joint Investigation of 26th January 2015.



Close-up: Illegal fitting on Santa Barbara Well 14S Flowline at Nembe - Bassambiri. Picture was taken during Joint Investigation of 26th January 2015.