


Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at K-Dere. Picture was taken during Joint Investigation of 5th January 2015.



Close-up: Illegal fitting on 28" Nkpoku-Bomu Pipeline at K-Dere. Picture was taken during Joint Investigation of 5th January 2015.