

Overview: Part of spill impact on 8" Umuechem-Nkpoku Pipeline Right of Way at Omunwei. Picture was taken during Joint Investigation of 16th April 2015.



<u>Close-up:</u> Illegal fitting on 8" Umuechem-Nkpoku Pipeline at Omunwei. Picture was taken during Joint Investigation of 16th April 2015.

1