



Overview: Part of spill impact within Kolocreek Manifold at Otusega. Picture was taken during Joint Investigation of 16th of April 2015.



Close-up: Former Location of missing Cork Valve Gauge (1) on Kolocreek Manifold at Otusega. Picture was taken during Joint Investigation of 16th of April 2015.



Close-up: Former Location of missing Cork Valve Gauge (2) on Kolocreek Manifold at Otusega. Picture was taken during Joint Investigation of 16th of April 2015.