



Overview: Part of spill impact on 20" Kolo Creek – Rumuekpe Pipeline Right of Way at Oruma. Picture was taken during Joint Investigation of 22nd of April 2015.



Close-up: Hacksaw Cut on 20" Kolo Creek – Rumuekpe Pipeline at Oruma. Picture was taken during Joint Investigation of 22nd of April 2015.