



Overview: Part of spill impact on 28" Bomu-Bony Trans Niger Pipeline Right of Way at Bodo West. Picture was taken during Joint Investigation of 26th April 2015.



Close-up: Illegal fitting on 28" Bomu-Bony Trans Niger Pipeline at Bodo West. Picture was taken during Joint Investigation of 26th April 2015.