



Overview: Part of spill impact on 20" Opukushi – Brass Creek Pipeline Right of Way at Tamogbene. Picture was taken during Joint Investigation of 15<sup>th</sup> May 2015.



Close-up: Illegal fitting on 20" Opukushi – Brass Creek Pipeline at Tamogbene. Picture was taken during Joint Investigation of 15<sup>th</sup> May 2015.