

<u>Close-up:</u> Tampered tree cap cover on Santa Barbara Well21T Wellhead at Nembe/Bassambiri. Picture was taken during Joint Investigation of 12th February 2015.