

Illegal fitting on 28" Nkpoku - Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 25th February 2015.



Close-up: Spill Source on 4" Illegal Pipe Fitting from the 28" Nkpoku - Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 25th February 2015.

1